
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Mike Viola
E-Mail: mviola@pppl.gov

Telephone: 609-243-3655
Fax: 609-243-2021

Part: /

Drawing ID: SE120-004

Revision: 2

Customer P.O.: S005243-F/Ln:3
Serial No./Qty:

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: The profile of the vessel skin exceeds the tolerance. The vessel profile checks from -0.317 / +0.397.

Refer to attached graphical report.

Proposed Disposition:

REVIEW FOR ACCEPTANCE

Number of additional pages: 0

Customer Disposition: ☐ Use As Is ☐ Rework ☐ Repair ☐ Scrap ☐ Replace

Technical Contact Approval:_____

Title:_____ **Date:**_____

Buyer Approval:_____

Title:_____ **Date:**_____

Major Tool Implemented By:_____

Title:_____ **Date:**_____

Nonconformance Report: Major Tool NC19704

This is for: **VVSA # 3 Profile** SE120-004

Problem:

The profile of the vessel skin exceeds the tolerance. The vessel profile checks from -0.317 / +0.397.
Refer to graphical report.

MTM Recommended Disposition:

Project Disposition:

Recent data associated with NC19990 reflects current conditions and supersedes this NCR.
This NC is closed.

Approvals:

Procurement Technical Representative

Responsible Line Manager: