| Contact: Mike Viola Telephone: 609-243-3655 E-Mail: mviola@pppl.gov Fax: 609-243-2021 Part: /VVSA # 2 Customer P.O.: S005243-F/Ln:2 Drawing ID: SE120-004 Revision: 2 Qty: 1 Reported By: DOUG MCCORKLE Telephone: 317-636-6433 E-Mail: dMcCorkle@MajorTool.com Fax: 317-634-9420 Problem: The length of port 17a checks from -0.208 / 0.234. The length of port 4a checks from -0.091 / +0.112. The length of port 4a checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 Customer Disposition: []Use As Is []Rework []Repair []Scrap []Replace | | | TON PLASMA PH | IYSICS LAB | | | | | |
|--|-------------------------------|---|---------------|-------------|--|----------------|------------|-------|--|
| Drawing ID: SE120-004 Revision: 2 Qty: 1 Reported By: DOUG MCCORKLE Telephone: 317-636-6433 E-Mail: dMcCorkle@MajorTool.com Fax: 317-634-9420 Problem: The length of port 17a checks from -0.208 / 0.234. The length of port 4a checks from -0.091 / +0.112. The length of port 4b checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | | | | | Telephone: 609-243-365 Fax: 609-243-202 | | | | |
| E-Mail: dMcCorkle@MajorTool.com Fax: 317-634-9420 Problem: The length of port 17a checks from -0.208 / 0.234. The length of port 4a checks from -0.091 / +0.112. The length of port 4b checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | | | | Revision: 2 | | | | n:2 | |
| The length of port 4a checks from -0.091 / +0.112. The length of port 4b checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | | | | | | | | | |
| The length of port 4b checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | Problem: | The length of port 17a checks from -0.208 / 0.234. | | | | | | | |
| Port Dome is slightly misaligned after trimmiming and re-installing (reference photos sent to PPPL via email 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | | The length of port 4a checks from -0.091 / +0.112. | | | | | | | |
| 07Jun2006) Proposed Disposition: Propose: USE AS IS Number of additional pages: 0 | | The length of port 4b checks from $-0.090 / +0.121$. | | | | | | | |
| Propose: USE AS IS Number of additional pages: 0 | | | | | | | | | |
| | | Propose: | | | | | | | |
| Customer Disposition: []Use As Is []Rework []Repair []Scrap []Replace | Number of additional pages: 0 | | | | | | | | |
| | Customer Dispo | osition: | [] Use As Is | [] Rework | [] Repair | [] Scrap | [] Replace | | |
| | | | | | | | | | |
| Technical Contact Approval: Title: Date: | Technical Contact Approval: | | | | | Title: | | Date: | |
| Buyer Approval: Title: Date: | Buyer Approval: | | | | | Title <u>:</u> | | Date: | |

Major Tool Implemented By:_____ Title: Date:_____

Nonconformance Report: Major Tool NC20069

This is for: VVSA # 2 Profile SE120-004

Problem:

The length of port 17a checks from -0.208 / 0.234. The length of port 4a checks from -0.091 / +0.112. The length of port 4b checks from -0.090 / +0.121. Port Dome is slightly misaligned after trimming and re-installing (reference photos sent to PPPL via email 07Jun2006)

MTM Recommended Disposition:

Use as is

Project Disposition:

Use as is

From: Thomas G. Brown
Sent: Thursday, July 27, 2006 12:12 PM
To: Michael E. Viola; Phil Heitzenroeder; Cole, Michael J.; Paul Goranson (goransonpl@ornl.gov); Bradley E. Nelson
Subject: VVSA2 NCR review

Mike Cole, Paul Goranson and I have reviewed the three MTM NCR's listed below and provide the following disposition and/or comments.

NCR 20069: We agree with the MTM disposition. Use as is.

Approvals:

Procurement Technical Representative

Responsible Line Manager: