



**Customer: ENERGY INDUSTRIES OF OHIO**

Contact: NANCY HORTON  
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314  
Fax: 216-328-2001

**Part: SE141-114 / MODULAR COIL WINDING FORM TYPE**

Drawing ID: MCWF TYPE-A XRAY MA Revision: 1  
W/O Links: 1-Type:W: 65709/5.0 Sub: 1

Customer P.O.: S005242-F/Ln:5  
Serial No./Qty: A5

Reported By: MIKE GRIFFITH  
E-Mail: mGriffith@MajorTool.com

Telephone: 317-636-6433  
Fax: 317-634-9420

**Problem: X RAY FAILURE ON:**

"T AREA", VIEW 41-45, POROSITY CLUSTER, LARGEST PORE MEASURES .090", AVERAGE PORE SIZE .060". APPROX. 15 PORES IN A 1 INCH CIRCLE. LOCATED BETWEEN TAPPED HOLE 43 AND 44. STRING OF POROSITY LEADING OFF OF CLUSTER APPROX. 4 INCHES.  
(see attachment)


**Proposed Disposition:**

Submit to Customer for Review.

Number of additional pages: 1 page RT attachment

**Customer Disposition:**    ☒ Use As Is    ☐ Rework    ☐ Repair    ☐ Scrap    ☐ Replace

The attached RT indications were reviewed by D. Williamson and discussed during a conference call attended by J. Chrzanowski, L. Sutton, F. Malinowski, L. Dudek, D. Williamson, T. Brown, and P. Heitzenroeder on 2/28/07. Dave notes that the stress in this region varies from 9-20 ksi. (62-138 MPa). As can be seen in the fracture plot, the region will meet the fatigue life criteria with these flaw sizes. (max. size is 0.090" : 1.5 mm)



Approved by:

Tech. Rep.:

RLM.

Major Tool Implemented By: \_\_\_\_\_


Title: \_\_\_\_\_

Date: \_\_\_\_\_



n:\mtmapps\Mtnonc14.qrp



## NC21264 – RT Rejections



View above is of a cluster of porosity between holes 43 and 44. The largest was sized at approximately .090”.



**From:** Williamson, David E. [williamsonde@ornl.gov]  
**Sent:** Tuesday, February 27, 2007 1:24 PM  
**To:** Phil Heitzenroeder  
**Subject:** RE: A5 PT Rejections - tentative A5 close-out telecon at 2:30 tomorrow

Phil,

My comments are:

Indication #1 - Datum-E, edge of flange, near tee hole #90, very low stress, acceptable

#2 - Datum-E, edge of flange, near tee hole #26, ~4-ksi, acceptable

#3 - Winding side-B, tee hole #80-81, stress=~3-ksi, acceptable

#4 - Winding side-A, base at tee hole #76, stress = ~3-ksi, acceptable

None of the indications occur in the high stress regions, tee hole #41-48, #61-65.

-David

---

**From:** Phil Heitzenroeder [mailto:pheitzen@pppl.gov]  
**Sent:** Tuesday, February 27, 2007 10:11 AM  
**To:** Williamson, David E.; Thomas G. Brown  
**Cc:** Lawrence E. Dudek; jchrzanowski@pppl.gov; Larry L. Sutton; fmalinowski@pppl.gov; Nelson, Brad E.; hneilson@pppl.gov  
**Subject:** FW: A5 PT Rejections - tentative A5 close-out telecon at 2:30 tomorrow

David,

Would you please review and comment? MTM expects to submit the A5 inspection data today and is asking if we can have the "close out" telcon at 2:30 tomorrow. Thanks

Phil

Is 2:30 tomorrow OK for everyone?

---

**From:** Griffith, Mike [mailto:MGriffith@majortool.com]  
**Sent:** Monday, February 26, 2007 4:04 PM  
**To:** NKHFlowen@aol.com; royjratc-aol-com-offsite; pdjord@sbcglobal.net  
**Cc:** bob.skelly@dcma.mil  
**Subject:** A5 PT Rejections

A5 inspection revealed very few rejectable indications. See attached.

**Mike Griffith**

Major Tool and Machine, Inc

Quality Control Manager

Tel: (317) 917-2612

Email: [mgriffith@majortool.com](mailto:mgriffith@majortool.com)



**From:** Griffith, Mike [mailto:MGriffith@majortool.com]  
**Sent:** Wednesday, February 28, 2007 12:12 PM  
**To:** NKHFlowen@aol.com; RoyJRATC@aol.com; pdjord@sbcglobal.net  
**Cc:** Phil Heitzenroeder; lsutton@pppl.gov; Larry Dudek; Williamson, David E.  
**Subject:** RT failure on A5

## Mike Griffith

Major Tool and Machine, Inc  
Quality Control Manager  
Tel: (317) 917-2612  
Email: [mgriffith@majortool.com](mailto:mgriffith@majortool.com)