PPPL NONCONFORMANCE REPORT NO: 3631 Open Date 02/15/06 Status 9 - Closed NCR 06-Workmanship/Needs Repair Trend Department NCSX Division NCSX Project Source/Org VENDOR Item Dwg/Part# SE123-164 and SE123-165 Procurement # PE006355-W Cost Center RAP# 3227 Job Doc # PE006355-W Vendor ADVANTECH INDUSTRIES, INC. RAP Title NCSX Type-C Modular Coil Chill Plates & Vacuum Vessel Cryostat Interface Parts HoldTag Applied Nonconforming Condition (include requirement(s) violated): Two of three Cryostat Interface Flanges (Dwgs. SE123-164 & SE123-165) arrived dented in the formed bellows which are welded onto the flanges. One has dents in two locations and the other has dents in one location (see attached photos). Sample Size Insp 3___ # Rejected 3 Lot Rejected Lot Size Recd 2 Validated Date 02/16/06 Reported By Dudek L Validated By Zatz I Disposition: Rework*_ Repair*_ Use As Is*_ Return To Vendor*_ Scrap*__ Use As Is Notify vendor of the problem to ensure remaining parts are corrected. This defect is not a problem since the pressure difference across the bellows is only a few inches of water. For rework or repair of vendor supplied equipments, fill in information below: Distribution Cog Dudek L \$G&A \$Est Labor #Hours Insp Zatz I \$Material \$Burden \$Total Proj. Doc Control (when closed) 02/15/06 Date QC Files Disposition By Dudek L Malsbury J 02/15/06 Date Supervisor's Concur Williams M Boscoe J Nelson B 02/15/06 Date Eng. Dept. Head Concur Williams M Goranson P WCO/Other Date N/A Viola M Williams M White A Lumberger J PQA/QC Mgr Dispos Concur Date Zatz I 03/02/06 Tyrrell M Malinowski F QC Field Verification By Date N/A