


VV support and diagnostic port interference





Port location after rotating port




Location Before:


Torordial angle 17 deg Poloidal angle 47 deg


Location after rotation


Torordial angle 18.5 deg Poloidal angle 56 deg

Port dia 10" od before and after












Reduced port dia. From 10" od to 8" od.

While a 10" od may work with additional tweaking reducing the od to 8" seems to assure clearance for now.







From Tom Brown's Power Point file



The modular coil shell opening and NBI port were reshaped to eliminate port interference with modular coils.


From Tom Brown's Power Point file





View from the bottom looking up

View looking down on the machine



? Coax Feed locations?

