## Open Date 10/10/05 PPPL NONCONFORMANCE REPORT NO: 3619 Status 9 - Closed NCR 01-Deviation From Doc/Proc Trend Department NCSX Division NCSX Project Source/Org VENDOR Item Dwg/Part# SE141-116, Rev. 6 Procurement # S005242-F Cost Center 9450 1\*\*\* 1404 RAP# 3209 Vendor Energy Industries of Ohio Job Doc # S005242-F RAP Title NCSX - Modular Coil Winding Forms HoldTag Applied Nonconforming Condition (include requirement(s) violated): (C-1 MCWF) A cooling tube hole (sheet 9, C-7) appears to be drilled at the wrong angle as it intersects the winding tee on the casting, but not on the model. Sample Size Insp 1 Lot Size Recd 1 ✓ Lot Reje... # Rejected Validated Date 10/06/05 Reported By Chrzanowski J Validated By Malinowski F Disposition: Rework\*\_\_ Repair\*\_\_ Use As Is\*\_\_ Return To Vendor\*\_\_ Scrap\*\_\_\_ Rework The hole was not drilled at wrong angle, but the cast wall, although in tolerance, was thicker than expected. When inspecting C1, NCSX also determined that the hole diameters (which conform to the drawing) need to be enlarged to provide adequate clearance from the coolant lines. Consequently, the drawings for all subsequent winding forms have been revised in NCSX-CSPEC-141-03, Rev. 10, to modify the hole locations and size, as shown in the attached drawing. For rework or repair of vendor supplied equipments, fill in information below: Distribution Cog <u>Heitzenroeder P</u> \$G&A \$Est Labor #Hours Insp Various \$Burden \$Total \$Material Proj. Doc Control (when closed) 11/30/05 Date QC Files Disposition By Heitzenroeder P Malsbury J 11/30/05 Date Supervisor's Concur Nelson B, NCSX Core Systems Mgr Boscoe J Chrzanowski J 12/01/05 Date Eng. Dept. Head Concur Williams M Sutton L WCO/Other Date N/A Malinowski F Nelson B Williams M Reiersen W PQA/QC Mgr Dispos Concur Date Malinowski F 12/01/05 Lumberger J Tvrrell M QC Field Verification By Date 12/01/05 Phelps C