## Open Date 10/10/05 PPPL NONCONFORMANCE REPORT NO: 3620 Status 9 - Closed NCR 01-Deviation From Doc/Proc Trend Department NCSX Division NCSX Project Source/Org VENDOR Item Dwg/Part# SE141-078, Rev. 1 Procurement # S005242-F Cost Center 9450 1\*\*\* 1404 RAP# 3209 Job Doc # S005242-F Vendor Energy Industries of Ohio RAP Title NCSX - Modular Coil Winding Forms HoldTag Applied Nonconforming Condition (include requirement(s) violated): (C-1 MCWF) The poloidal break shim does not follow the contours of the casting as shown on SE141-078, Rev. 1 and in the corresponding model. Sample Size Insp 1\_\_\_\_ ✓ Lot Reje... # Rejected Lot Size Recd 1 Validated Date 10/06/05 Reported By Nelson B Validated By Malinowski F Disposition: Rework\*\_\_ Repair\*\_\_ Use As Is\*\_\_ Return To Vendor\* Scrap\* Use As Is The shims for C1 and C2 are both machined similarly (i.e., not following casting contours) due to the unavailability of STEP files when these parts are machined. Consequently, the shims for C1 and C2 will be accepted "as is" and NCSX will compensate for this condition when winding these coils. CAD files for machining the shims for all three casting types are now available and posted; all remaining shims are to be machined to follow the casting contours per these files. Cost of rework: Shimming of the windings to compensate is estimated to take 4 hrs. @ \$85/hr=\$340. For rework or repair of vendor supplied equipments, fill in information below: Distribution Cog <u>Heitzenroeder P</u> #Hours \$Est Labor \$G&A Insp Various \$Total \$Material \$Burden \$340 Proj. Doc Control (when closed) 11/30/05 Date QC Files Disposition By Heitzenroeder P Malsbury J 11/30/05 Date Supervisor's Concur Nelson B, NCSX Core Systems Mg Boscoe J Heitzenroder P 11/30/05 Date Eng. Dept. Head Concur Williams M Sutton L WCO/Other Date N/A Malinowski F Williams M Reiersen W Nelson B PQA/QC Mgr Dispos Concur Date Malinowski F 11/30/05 Lumberger J Chrzan J/Raftop QC Field Verification By Date Malinowski F 11/30/05 Tvrrell M