PPPL NONCONFORMANCE REPORT NO: 3630 Open Date 02/02/06 Status 9 - Closed NCR 01-Deviation From Doc/Proc Trend Department **Division** NCSX Project NCSX Source/Org FABRICATION, OPERATIONS & MAINTENANCE Item Dwg/Part# SE142C-134R2&SE142-135R Procurement # PE006055-W Cost Center RAP# 3207 Job Doc # D-NCSX-MCF-001 Vendor RAP Title Modular Coil Fabrication - Winding Form Preparation Activities HoldTag Applied Nonconforming Condition (include requirement(s) violated): The lower lead block parts for the C-Type NCSX modular coils are not in accordance with the drawing details. See Attachment 1 for details. (For QA reference: JP Pattern, PE006055-W) Sample Size Insp 7 Lot Size Recd 12 Lot Rejected # Rejected Validated Date 02/01/06 Reported By Phelps C Validated By Zatz I Disposition: Rework*_ Repair*_ Use As Is*_ Return To Vendor*_ Scrap*__ Rework The manufacturer fabricated the parts correctly to the revision of the drawing that he was given. Sometime during the manufacturing process, NCSX made drawing changes that never got to the vendor. Parts are to be modified in-house to revised drawings. For rework or repair of vendor supplied equipments, fill in information below: <u>Distribution</u> Cog J. Chrzanowski \$G&A ____ #Hours \$Est Labor Insp Phelps/Boscoe \$Material \$Burden \$Total Proj. Doc Control (when closed) Date 03/02/06 Chrzanowski J QC Files Disposition By Malsbury J 03/02/06 Date Supervisor's Concur Dudek L Boscoe J 03/02/06 T. Meighan Date Eng. Dept. Head Concur Williams M Heitzenroeder P WCO/Other Date N/A Williams M Tyrrell M PQA/QC Mgr Dispos Concur Date Boscoe J 03/09/06 QC Field Verification By Date 05/10/06 Phelps C

NCR 3630 Details - Attachment 1

SE142C-134 Rev. 2 "Modular Coil Type-C Side A Lower Lead Block Detail"

Area C-3

- 1. Drawing calls for two 0.63" dia. holes with a tolerance of \pm 0.01", holes measure 0.60".
- 2. Drawing calls for 1.0" dia. holes for a depth of 0.375" with a tolerance of ± 0.01 ", holes measure 0.90" with a depth of 0.563".

Section A-A

1. Drawing calls for a thickness of 0.69" with a tolerance of +/- 0.01", thickness measures 0.94".

Section D-D

1. Drawing calls for a thickness of 1.02" with a tolerance of +/- 0.01", thickness measures 0.94".

A sampling of four out of the six pieces received were measured and all four were found to be out of tolerance as detailed above.

SE142C-135 Rev. 1 "Modular Coil Type-C Side B Lower Lead Block Detail"

Area D-5

- 1. Drawing calls for two 0.63" dia. holes with a tolerance of \pm 0.01", holes measure 0.59".
- 2. Drawing calls for 1.0" dia. holes for a depth of 0.375" with a tolerance of ± 0.01 ", holes measure 0.90" with a depth of 0.563".

Section A-A

1. Drawing calls for a thickness of 0.69" with a tolerance of ± 0.01 ", thickness measures 0.94".

A sampling of three out of the six pieces received were measured and all three were found to be out of tolerance as detailed above.