

Status	2 - Disposition Needed		Trend	01-Deviation From Doc/Proc	
Department	NCSX		Division	WBS 141	
Source/Org	FABRICATION, OPERATIONS & MAINTENANCE				
Item Dwg/Part#	SE142C-270 Rev. 0	Procurement #		Cost Center	
RAP#	3234	Job Doc #	D-NCSX-MCF-004	Vendor	VARIOUS
RAP Title	Modular Coil Fabrication - Post VPI Activities				

HoldTag Applied

Nonconforming Condition (include requirement(s) violated):

The following additional parts for the NCSX modular coil final winding clamp assemblies exhibit a magnetic permeability higher than the maximum allowed per NCSX-ASPEC-GRD-03 paragraph 3.3.1.1 (permeability shall not exceed 1.02). See NCR 3634 for list of additional final winding clamp parts that are over the magnetic permeability limit.
 PART #s 3 AND 6 (SEE ATTACHED FOR DETAILS.)

The following parts were found to be acceptable.
 PART #9 (SEE ATTACHED FOR DETAILS.)

REV 1: ADDITIONAL PARTS RECEIVED AND INSPECTED. SEE ATTACHMENT.
 REV 2: Final winding clamp assembly redesigned, see attachment for revision details. Also see NCR 3634 as it deals with this same issue.
 REV 3: Further investigation (part 6 only) with greater details per NCSX Engineering request, see page 2 of Attachment for specifics.

Lot Size Recd	0	Sample Size Insp	0	<input type="checkbox"/> Lot Rejected	# Rejected	0
Reported By	Phelps C	Validated By	Boscoe J	Validated Date	10/04/07	

~~Disposition: Rework* ___ Repair* ___ Use As Is* ___ Return To Vendor* ___ Scrap* ___~~

Awaiting test results from outside laboratory to determine whether the permeability of the 316ss parts can be used as is without further work.
 C. Phelps, 4/3/07 - Larry D. said Phil will address when he returns.

Please use p. 2 for disposition and approvals .

~~For rework or repair of vendor supplied equipments, fill in information below:~~

#Hours	_____	\$Est Labor	_____	\$G&A	_____
\$Material	_____	\$Burden	_____	\$Total	_____
Disposition By	_____	Date	_____		
Supervisor's Concur	_____	Date	_____		
Eng. Dept. Head Concur	_____	Date	_____		
WCO/Other	_____	Date	_____		
PQA/QC Mgr Dispos Concur	_____	Date	_____		
QC Field Verification By	_____	Date	_____		

Distribution

Cog J. Chrzanowski
Insp C. Phelps
 Proj. Doc Control (when closed)
 QC Files
 Malsbury J
 Boscoe J
 T. Meighan
 Dudek L
 Williams M
 Tyrrell M
 Simmons B

Disposition: Rework___ Repair ___ Use As Is___ Return to Vendor___ Scrap___



For rework or repair of vendor supplied equipment, fill in information below:

Hours _____ \$ Est Labor _____ \$ G&A _____
\$ Material _____ \$ Burden _____ \$ Total _____

Disposition by _____

~~Supervisor's Concurrence~~ _____

Eng. Dept. Head Concurrence _____

Other (i.e., WCO/FPE) Concurrence _____

PQA/QC Mgr Disposition Concurrence _____

QA Field Verification by _____

NCR 3639 ATTACHMENT, R3 (p. 1 of 2)

The following additional parts for the NCSX modular coil final winding clamp assemblies exhibit a magnetic

Permeability higher than the maximum allowed per NCSX-ASPEC-GRD-03 paragraph 3.3.1.1 (permeability shall not exceed 1.02). See NCR 3634 for a list of additional final winding clamp parts that are over the magnetic permeability limit.

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
3	Bushing Spacer	805	30	(5) >1.06, <1.08 (23) >1.08, <1.09
	(silver plated 316)			(2) >1.09, <1.10

6	Keeper Screw (silver plated 316)	1756	40	(21) >1.02, <1.03 (7) >1.03, <1.04
		1464 (2nd shipment)	80	(4) <1.02 (36) >1.02, <1.03 (24) >1.03, <1.04 (14) >1.04, <1.05 (1) >1.05, <1.06

The following parts were found to be acceptable:

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
9	Flat Washer (316)	1980	40	(40) <1.02

REV 2: The final winding clamp has been redesigned requiring new Part 3, the new shipment of Part 3 are below 1.02 Mu (see sampling results below). Part 6 remains unchanged and cannot be annealed due to the silver plating. See results above and NCR 3634 for additional permeability readings on the balance of Part 6.

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
New - 3	Bushing Spacer	910	72	(72) <1.02 Mu

REV 3: 10/4/07 – Upon further discussion and investigation with NCSX Engineering an additional sample of remaining “keeper screws” (pt. #6) was conducted with the intention of better defining specifically which areas of these parts are exhibiting high magnetic permeability. See details of sampling and drawing below.

A quantity of 100 pieces of pt. #6 remain in their original packaging from vacuum prep., a sample of 12 pieces was inspected with the following results.

<u>Sample #</u>	<u>Number of spots >1.02 Mu</u>	<u>Permeability of spots</u>
1	2	Both spots >1.02, <1.03 Mu
2	Entire top face	Entire top surface >1.02, <1.03 Mu
3	2	1 spot >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
4	2	Both spots >1.02, <1.03 Mu
5	3	All spots >1.02, <1.03 Mu
6	0	Entire part <1.02 Mu
7	4	3 spots >1.02, <1.03 Mu; 1 spot >1.04, <1.05 Mu
8	3	All spots >1.02, <1.03 Mu
9	3	2 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu

NCR 3639, Attachment, R3 (p. 2 of 2)

10	5	4 spots >1.02, <1.03 Mu; 1 spot >1.03 , <1.04 Mu
11	6	5 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
12	6	4 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu; 1 spot >1.04, <1.06

The worst case possible from the data above appears to be the entire top surface of the part at just under 1.06 Mu. Only the outer surfaces of the part was able to be measured due to the configuration of the gauge and part, none of the threads exhibited any permeability and most of the pieces sampled only had a few spots on the top surface around the spanner wrench holes, see drawing below.

