NCSX ENGINEERING CHANGE NOTICE (ECN) ECN # 5379R1

COGNIZANT INDIVIDUAL: Mike Cole

ECN TITLE: Vacuum Vessel Support Rods

CC/WP/Job: /1806 AREA OR PROJECT: NCSX

LIMITATION OF SCOPE - NOTE: A Work Planning Form is NOT required if the total change to be accomplished (ENG-032):

- Is not large or complex or does not represent a new installation into a usable space
- Does not have a significant ES&H impact
- Does not involve tritium or other radioactive contaminated or activated equipment
- Does not impact multiple projects, systems, or groups

OR does not change the scope or intent of the original design.

Responsible Line Manager CONCURRENCE: __Phil Heitzenroder____ (Signature indicates that no Work Planning form is required.)

If non-concurrence or associated with a work planning form, enter the WP number:

DRAWING(S)	Current	TITLE
AFFECTED NUMBER:	Revision	
SE124-051	1	VERTICAL UPPER SUPPORT ASSEMBLY
SE124-054	0	VERTICAL LOWER SUPPORT ASSEMBLY
SE124-055	0	VERTICAL SUPPORT CLEVIS

DESCRIPTION OF CHANGE: (state drawing no., zone. group, or list attachments)

SE124-051

CHANGED HAIRPIN TO COTTER PIN

SE124-054

CHANGED HAIRPIN TO COTTER PIN

SE124-055

3/4-10UNC WAS 3/4-16UNF

REASON FOR CHANGE:

SE124-051 – To eliminate the possibility retaining pin from slipping off.

SE124-054 – To eliminate the possibility retaining pin from slipping off.

SE124-055 - To match threads to the bosses on the vacuum vessel. Per NCR# 3664

NCSX ENGINEERING CHANGE NOTICE (ECN) ECN # 5379R1

ENGINEERING CHANGE NOTIC	E APPROVALS: DATE: 7/18/2008
COGNIZANT INDIVIDUAL MAK	ING CHANGE:
RESPONSIBLE LINE MANAGER:	:
☑ Update Drawings Immediately	☐ Defer Update and Use ECN Stamp
Other Comments:	

tatus	NFORMANCE REPORT NO: 3664 Open Date 07/21/06 5 - Corrective Action Needed Trend 05-Design Interferance
epartment	NCSX Division NCSX Project
ource/Org	NCSX Project
em Dwg/Part#	SE120-004 R2 Pt.s 48 to 51, S
Sost Center	WBS/Other 00/00/00
AP# 32	
	Period Assembly Component Receipt Inspection
HoldTag Ap	plied
VVSA-1, 2, 3) The Clevis Bosses (pt.s Clevises threading	Condition (include requirement(s) violated): threads on the Vertical Support Clevises (pt. 1 Dwg. SE124-055 R0) do not match up with the threads on the 48 to 51 Dwg. SE120-004 R2). Drawing SE124-051 R0 "Vertical Support Assembly" shows the Vertical Support into the Clevis Bosses. The Clevis Bosses are installed on the vacuum vessel (VVSA-1). This condition will most 2 & VVSA-3 as well. The threads on each part are in accordance with the drawing details.
Vertical Support Cl Clevis Boss A, Clevis Boss B, Clevis Boss C, Clevis Boss D,	evis, 0.75 - 16 UNF threads, Qty. 12, pt. 1 0.75 - 10 UNC threads, Qty. 2, pt. 48 0.75 - 10 UNC threads, Qty. 2, pt. 49 0.50 - 13 UNC threads, Qty. 2, pt. 50 0.50 - 13 UNC threads, Qty. 2 ,pt. 51
ot Siza Pacd	0 Sample Size Insp 0 Lot Rejected # Rejected 0
Lot Size Recd	
Reported By _	Edwards J Validated By Phelps C Validated Date 07/21/06
<u>Distribution</u>	Cog M. Viola Insp Phelps/Boscoe
Proi. Doc	Control (when closed) QC Files Malsbury J Boscoe J
oj. 200	Times (misself y bosons)

n: Rework* Repair* Use As	Is* Return To Vendo	r* Scrap*	F	Repair
s threads with coarse threads.				
CR willl remain open until correctve a /20/06 - This corrective action will no his work is at least 6-months away as /18/08 - Per Mike V. verbal, this work	ot take place until assembly s of 6/12/07 (C. Phelps)			
For rework or repair of vendor #Hours			elow:	
For rework or repair of vendor #Hours \$Material	supplied equipments, fi \$Est Labor \$Burden	\$G&A		
#Hours	\$Est Labor \$Burden	\$G&A		
#Hours \$Material	\$Est Labor	\$G&A		07/25/06 07/25/06
#Hours \$Material Disposition By	\$Est Labor \$Burden Viola M	\$G&A	Date	07/25/06
#Hours \$Material Disposition By Supervisor's/RLMs Concur	\$Est Labor \$Burden Viola M Dudek L	\$G&A	Date Date	07/25/06 07/25/06
#Hours \$Material Disposition By Supervisor's/RLMs Concur Eng. Dept. Head Concur	\$Est Labor \$Burden Viola M Dudek L Williams M	\$G&A	Date Date Date	07/25/06 07/25/06