Major Tool & Machine, Inc. 1458 East 19th Street

Page: 1 Date: 10/25/05 MTM N/C: 18459 **User ID: MCCORKLE** Indianapolis, IN 46218-4289

Contact: Mike Viola E-Mail: S-04286-F			Telephone: (609) 243-3655 Fax: (609) 243-3248			
Part: / Drawing ID: SE120-004	Revision: 2		Customer P.C Serial No	D.: S005243-F/Ln:7 p.: 3/7		
Reported By: DOUG MCCORKLE E-Mail: dMcCorkle@MajorTool.c	om			ne: 317-636-6433 ax: 317-634-9420		
Problem: Profile requirement of 0.13	88 (+ Unilateral) che	ecks +0.275 / -0.	101			
	after the port is insta	s structurally consides. Both ends	mplete). The part (radii) are within aspected (without	t is currently out of n tolerance. This reworking the port sub-		
Customer Disposition: [ ] Use As Is	[ ] Rework	[ ] Repair	[ ] Scrap	[ ] Replace		
Technical Contact Approval:			Title:	Date:		
Buyer Approval:			Title:	Date:		
Major Tool Implemented By:			Title:	Date:		

 $n:\ \ mapps\\ Mtnonc14.qrp$ 

Project Disposition:
Use as is:
The data was taken on two fully welded port assemblies (port 12A and port 12B) that had not yet been welded to the vacuum vessel shell. Although there are a few points that are out of tolerance, recommendation is to accept the parts as is. The vast majority of out of tolerance points are away form the modular coil which should not impose significant problems. The VV heating/cooling mounting flange (se123-167) that will be welded to the vertical ports at final assembly at PPPL will need to have its inner flange surface trimmed to match the surface of the port.
Approvals:
Procurement Technical Representative
Responsible Line Manager:

Nonconformance Report: Major Tool NC18459.
This is for the port 12A out of tolerance condition on the first VVSA (MTM lot 7)