
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: fmalinowski@pppl.gov
E-Mail: S-04286-F

Telephone: 609-243-2441
Fax: 609-243-2021

Part: SE122-049
Drawing ID: SE122-049

Revision: 1

Customer P.O.: S005243-F/Ln:8
Serial No.: 126/8, 145/8, 126/9, 145/9

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: REJECTED MAGNETIC PERMEABILITY OF 1.02 MAX
CHECKS ACTUAL 1.05-1.10

Proposed Disposition:

Customer Disposition Required.

Number of additional pages: 0

Customer Disposition: Use As Is Rework Repair Scrap Replace

The 5 MTM NCRs are acceptable. They flanges and covers are located far enough from the plasma and in a region of low field that their effect on error fields is estimated to be minimal (<0.1G at plasma).

PPPL Technical Approval: _____

Title: _____ **Date:** _____

PPPL RLM Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____