
Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-115 / MODULAR COIL, TYPE B

Drawing ID: SE141-102 Revision: 3
W/O Links: 1-Type:W: 65708/3.0 Sub: 0

Customer P.O.: S005242-F/Ln:3
Serial No./Qty: B3

Reported By: MIKE GRIFFITH
E-Mail: mGriffith@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: SEVERAL ITEMS NOTED DURING VISUAL REVIEW OF CASTING. SEE ATTACHMENT.
Rev. 1 - added pages 9 & 10 to the attachment. (1-2-07)

Proposed Disposition:

MTM PROPOSES TO ACCEPT AS IS.

Number of additional pages: 10 page attachment

Customer Disposition: Use As Is Rework Repair Scrap Replace

All the visual defects were reviewed during a conference call on 1/5/07 attended by N. Horton, R. Sheppard, M. Griffith, L. Sutton, J. Chrzanowski, F. Malinowski, and P. Heitzenroeder. The notch defects shown on Pg. 9 require rework – MTM is requested to grind the sharp corners of the notch to a 0.060” (min.) radius. The others are surface defects, referred to as “tooling marks” by MTM, and are caused imperfect machining setups, especially as MTM added new milling machines to broaden the number of machines available. They were described as being very shallow – 0.002-0.010” deep. J. Chrzanowski agreed that they can be accepted as is, and will examine them when the winding form arrives and determine if some should be filled with epoxy.

Accepted by:

Tech. Rep.

RLM



Major Tool Implemented By: _____ **Title:** _____ **Date:** _____




Tool Gouges on E side Long Leg near radius





Tool Gouges on E side Long Leg near radius





NC20920 – B3 Visual Review



.400" distance from short leg to VPI groove (sheet 2, zone G7)

There is an area on the Datum D side from T hole 81 to 86 that checks as small as .300".
The transition has been blended smooth.


There is an area on the Datum D side from T hole 70 to 73 that checks as large as .506".

(SEE NC20917 step 110)






Tool Gouges on D side Long Leg near radius








Tool Gouges on D side Long and Short Legs near radius





Tool Gouges on D side Long and Short Legs near radius





Oversize area in hole #27 in Datum E flange. (reported on NC20917 step 730)



Undercut areas adjacent to .12" radius of Long Leg

Datum E Side

E93 – E4 (.010" - .017")

E53 – E55 (.010" - .011")

Datum D Side

D42 – D45 (.010" - .024")

D58 – D60 (.010" - .011")

D62 – D66 (.010" - .015")

D73 – D75 (.010" - .025")

D84 – D88 (.010" - .022")



NC20920 – B3 Visual Review





The picture to the left is of the port opening on the Datum D flange just beneath the Lead Block pad.

A programming error resulted in too much material being removed during the rough machining operation. An area on both sides of the port did not clean up.

One area measures approximately .25" x .25" and the other is .35" x .35". Both cutter marks extend through the opening the thickness of the casting wall.





From the orientation shown, the 1-8" hole pattern was shifted .25" down. This hole pattern, per the model, was not centered about the 2.5" hole prior to this shift.

Feedback on Vacuum Vessel support pads per request of weekly quality meeting.

(EIO, MTM) Provide documentation of completion of corrective action for EIO CA 090606(NCR) for B-3 & B-6 Vacuum Vessel support pads deviations.
Status: (Open) MTM confirms that the center hole position is fixed but the tapped hole pattern is being shifted as needed (applies to all Type B castings). EIO/MTM will provide proposed shifted locations prior to drilling. On B3 & B6 it's likely that one hole cannot be drilled (corner missing). The CA will remain open until after B6 is completed.