## PPPL NONCONFORMANCE REPORT NO: 3629 Open Date 01/09/06 Status 5 - Corrective Action Needed 01-Deviation From Doc/Proc Trend Department **NCSX** Division NCSX Project Source/Org FABRICATION, OPERATIONS & MAINTENANCE Item Dwg/Part# SE141-103 Procurement # D-NCSX-MCF-001 R.2 Cost Center RAP# 3207 Job Doc # D-NCSX-MCF-001 Vendor RAP Title Modular Coil Fabrication - Winding Form Preparation Activities HoldTag Applied Nonconforming Condition (include requirement(s) violated): The polodial break nut bearing plates on the C1 modular coil winding form has a magnetic permeability that is over the maximum of 1.02 as stated in NCSX-ASPEC-GRD-03 paragraph 3.3.1.1. There are six bearing plates on the winding form. All six plates have permeability readings greater than 1.02 but less than 1.05. Severn gauge #5111 was used and has the following inserts for readings: 1.01, 1.02, 1.05, 1.2, 1.8, 2.0, 2.2, 3.0 and 3.5. All six plates are installed on the winding form. Sample Size Insp Lot Rejected # Rejected Lot Size Recd 6 6 Validated Date 01/09/06 Reported By Phelps C Validated By Boscoe J Disposition: Rework\* Repair\* Use As Is\* Return To Vendor\* Scrap\* Rework The bearing plates will be replaced during the time that the new hardware for the poloidal break is changed out. For rework or repair of vendor supplied equipments, fill in information below: Distribution Cog J. Chrzanowski \$G&A #Hours \$Est Labor Insp Phelps/Boscoe \$Material \$Burden \$Total Proj. Doc Control (when closed) 03/02/06 Chrzanowski J Date QC Files Disposition By Malsbury J 03/02/06 Date Supervisor's Concur Dudek L Boscoe J 03/02/06 Heitzenroeder P Date Eng. Dept. Head Concur Williams M Williams M WCO/Other Date N/A Tyrrell M PQA/QC Mgr Dispos Concur Boscoe J Date 03/09/06 QC Field Verification By Date