

Status	2 - Disposition Needed		Trend	01-Deviation From Doc/Proc	
Department	NCSX		Division	WBS 141	
Source/Org	FABRICATION, OPERATIONS & MAINTENANCE				
Item Dwg/Part#	SE142C-270 Rev. 0	Procurement #		Cost Center	
RAP#	3234	Job Doc #	D-NCSX-MCF-004	Vendor	VARIOUS
RAP Title Modular Coil Fabrication - Post VPI Activities					

☐ HoldTag Applied
Nonconforming Condition (include requirement(s) violated):

The first shipment of NCSX modular coil final winding clamp assemblies, and related purchased hardware exhibits a magnetic permeability higher than the maximum allowed per NCSX-ASPEC-GRD-03 paragraph 3.3.1.1 (permeability shall not exceed 1.02). Unless otherwise noted all material is type 316 stainless steel See attached list for details.

REV 1: Parts 3 and 6 are silverplated and were verbally reported as not being able to be annealed without damage.

SEE PAGE 2 FOR ADDITIONAL REVISIONS.

REV 2: Final winding clamp assembly redesigned, see attachment for revision details. Also see NCR 3639 as it deals with this same issue.

REV 3: Further investigation (part 6 only) with greater details per NCSX Engineering request, see page 2 of attachment for specifics.

Lot Size Recd	0	Sample Size Insp	0	<input type="checkbox"/> Lot Rejected	# Rejected	0
Reported By	Phelps C	Validated By	Boscoe J	Validated Date	10/04/07	

~~Disposition: Rework* ___ Repair* ___ Use As Is* ___ Return To Vendor* ___ Scrap* ___~~

(Rev 0) Rework by removing permeability using vacuum oven cycle 800-1000 deg. C @ 1 hour. (Labor = 40 hours)

(Rev 1) Awaiting test results from outside laboratory to determine whether the permeability of the 316ss parts can be used "as is" without further work.

Note: C. Phelps, 4/3/07 - Larry said Phil will address this when he returns.

Please use p. 2 for disposition and approvals .

~~For rework or repair of vendor supplied equipments, fill in information below:~~

#Hours	_____	\$Est Labor	_____	\$G&A	_____
\$Material	_____	\$Burden	_____	\$Total	_____

Disposition By	_____	Date	_____
Supervisor's Concur	_____	Date	_____
Eng. Dept. Head Concur	_____	Date	_____
WCO/Other	_____	Date	_____

PQA/QC Mgr Dispos Concur	_____	Date	_____
QC Field Verification By	_____	Date	_____

Distribution

Cog J. Chrzanowski

Insp C. Phelps

Proj. Doc Control (when closed)

QC Files

Malsbury J

Boscoe J

T. Meighan

Williams M

Dudek L

Tyrrell M

Simmons B

Disposition: Rework____ Repair ____ Use As Is____ Return to Vendor____ Scrap____

For rework or repair of vendor supplied equipment, fill in information below:

Hours _____ \$ Est Labor _____ \$ G&A _____
\$ Material _____ \$ Burden _____ \$ Total _____

Disposition by _____

~~Supervisor's Concurrence~~ _____

Eng. Dept. Head Concurrence _____

Other (i.e., WCO/FPE) Concurrence _____

PQA/QC Mgr Disposition Concurrence _____

QA Field Verification by _____

NCR 3634, Attachment, R3 (p. 1 of 2)

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
2	Bar, Clamp	175	21	(12) >1.10, <1.15 (4) >1.15, <1.2 (5) >1.2, <1.8
3	Bushing Spacer (Silver Plated 316)	1	1	(1) >1.06, <1.08
4	Washer, Convex	1610	100	(40) <1.02 (60) >1.02, <1.03
5	Washer, Concave	1610	100	(6) >1.02, <1.03 (9) >1.03, <1.04 (30) >1.04, <1.05 (30) >1.05, <1.06 (25) >1.06, <1.08
6	Keeper Screw (Silver Plated)	4	4	(1) >1.02, <1.03 (1) >1.03, <1.04 (2) >1.04, <1.05
7	Clamp Swivel	1	1	(1) >1.03, <1.04
10	3/8-16 x 1 ¼ SH	882	44	(41) >1.02, <1.03 (3) <1.02
11	3/8 x 3/8 shoulder	188	20	(1) >1.02, <1.03 (1) >1.03, <1.04 (3) >1.04, <1.05 (6) >1.05, <1.06 (6) >1.06, <1.08 (3) >1.08, <1.09

The following parts were found to be acceptable.

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
8	Belleville Washers	~10,000	~200	(~200) <1.02 (Inconel)
12	¼-20 x ½ BH	1850	100	(100) <1.02

REV 2: The final winding clamp has been redesigned eliminating parts 4, 5, and 11. Parts 3 and 7 have been redesigned, the new shipments of parts 3 and 11 are below 1.02 Mu (see sampling results below). Parts 2 and 10 have been annealed in accordance with Rev 0 disposition and are all below 1.02 Mu. Part 6 remains unchanged and cannot be annealed due to the silver plating. See results above and NCR 3639 for additional permeability readings on the balance of Part 6.

<u>Part #</u>	<u>Part Type</u>	<u>Quantity</u>	<u>Sample Size</u>	<u>Results</u>
New - 3	Bushing Spacer	910	72	(72) <1.02 Mu
New - 7	Clamp Swivel	920	80	(80) <1.02 Mu

REV 3: 10/4/07 – Upon further discussion and investigation with NCSX Engineering an additional sample of remaining “keeper screws” (pt. #6) was conducted with the intention of better defining specifically which areas of these parts are exhibiting high magnetic permeability. See details of sampling and drawing below.

A quantity of 100 pieces of pt. #6 remain in their original packaging from vacuum prep., a sample of 12 pieces was inspected with the following results.

<u>Sample #</u>	<u>Number of spots >1.02 Mu</u>	<u>Permeability of spots</u>
1	2	Both spots >1.02, <1.03 Mu
2	Entire top face	Entire top surface >1.02, <1.03 Mu
3	2	1 spot >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
4	2	Both spots >1.02, <1.03 Mu
5	3	All spots >1.02, <1.03 Mu
6	0	Entire part <1.02 Mu
7	4	3 spots >1.02, <1.03 Mu; 1 spot >1.04, <1.05 Mu
8	3	All spots >1.02, <1.03 Mu
9	3	2 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
10	5	4 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
11	6	5 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu
12	6	4 spots >1.02, <1.03 Mu; 1 spot >1.03, <1.04 Mu; 1 spot >1.04, <1.06

The worst case possible from the data above appears to be the entire top surface of the part at just under 1.06 Mu. Only the outer surfaces of the part was able to be measured due to the configuration of the gauge and part, none of the threads exhibited any permeability and most of the pieces sampled only had a few spots on the top surface around the spanner wrench holes, see drawing below.

