PPPL NONCONF	ORMANCE REPORT	NO: 3684	Open Date	11/30/06	
_	- Corrective Action Needed		Trend 01	-Deviation From Doc/Pr	COC
_	CSX		Division W	BS 141	_
_	ENDOR				
Item Dwg/Part# S	E141-114, r8 - MCWF A-4	Procurement #	S005242-F	Cost C	9450 1*** 1404
RAP# 3209	Job Doc # S005242-F	Vendor	Energy Indust	ries of Ohio	
RAP Title NCSX - N	lodular Coil Winding Forms				
☐ HoldTag Appli	ed				
Nonconforming Co	ndition (include requiren	nent(s) violated)	:		
1) Between Holes #86 portion of the leg. MTI just at the upper limit There is a similar, thou	following conditions (photos at to #94 the legs of the Tee (see A's measurements of the long of the tolerance of .020" profiling more shallow, "gully" on the way at	eptum) have a step leg in this area sho e equally distribute ne short leg.	down area that w it .002" to .00 d bilaterally (+/	dips, on the long leg, 3" above nominal, so the 010"), to as much as	he "gully" ranges from .010", .020" below that tolerance.
Lot Size Recd Reported By Phe	1 Sample Size		_ Lo owski F	t Rejected # Validated D	Rejected 1 1 ate 11/27/06
Disposition: Rework	 Repair* Use As Is*	Return To Vendo	or* Scrap*	_	Rework
condition will be discu	ssed with EIO/MTM during the	next Quality Call to	avoid this cond	ition with ruture casting	<b>J</b> S.
For rework or repair o	f vendor supplied equipmen	ts, fill in informati	on below:	<u>                                     </u>	<u>Distribution</u>
#Hours	\$Est Labor	\$	G&A		Cog Heitzenroeder P
\$Material	\$Burden	\$	Total\$42	5	Insp Chrzanowski Proj. Doc Control (when
Disposition By	Heitzenroeder F	)	Date	11/00/07	closed) QC Files
Supervisor's Conc	<b>ur</b> Nelson B		Date	= 11/30/00 1	Malsbury J Boscoe J
Eng. Dept. Head Co	oncur Williams M		 Date		Sutton L
WCO/Other	N/A		—— Date	<b>`</b>	Nelson B Reiersen W
PQA/QC Mgr Dispo	os Concur <u>Malinowski</u> F	:	Da	te <u>12/08/06</u>	Williams m Lumberger J Tyrrell M Malinowski F
			Da	te	Phelps C