

Status	9 - Closed NCR	Trend	01-Deviation From Doc/Proc
Department	NCSX	Division	WBS 141
Source/Org	VENDOR		
Item Dwg/Part#	SE141-114, r8 - MCWF A-4	Procurement #	S005242-F
		Cost Center	9450 1*** 1404
RAP#	3209	Job Doc #	S005242-F
		Vendor	Energy Industries of Ohio
RAP Title	NCSX - Modular Coil Winding Forms		

HoldTag Applied

Nonconforming Condition (include requirement(s) violated):

MCWF A-4 shows the following conditions (photos attached) exceeding the tolerances of SE141-114, R8:
 1) Between Holes #86 to #94 the legs of the Tee (septum) have a step down area that dips, on the long leg, .008" to .028" from the flat portion of the leg. MTM's measurements of the long leg in this area show it .002" to .003" above nominal, so the "gully" ranges from .010", just at the upper limit of the tolerance of .020" profile equally distributed bilaterally (+/- .010"), to as much as .020" below that tolerance. There is a similar, though more shallow, "gully" on the short leg.
 2) Between Holes #48 & #52 the radius between the long and short legs of the Tee exceeds the specified .11" +/- .01".

Lot Size Recd	1	Sample Size Insp	1	<input type="checkbox"/> Lot Rejected	# Rejected	1
Reported By	Phelps C	Validated By	Malinowski F	Validated Date	11/27/06	

Disposition: Rework* Repair* Use As Is* Return To Vendor* Scrap* Rework

The "gully" areas should be filled in with CTD 540 epoxy / glass bead to provide an even surface and support for the winding. This condition will be discussed with EIO/MTM during the next Quality call to avoid this condition with future castings.

For rework or repair of vendor supplied equipments, fill in information below:

#Hours	_____	\$Est Labor	_____	\$G&A	_____
\$Material	_____	\$Burden	_____	\$Total	\$425

Disposition By	Heitzenroeder P	Date	11/30/06
Supervisor's Concur	Nelson B	Date	11/30/06
Eng. Dept. Head Concur	Williams M	Date	12/01/06
WCO/Other	N/A	Date	_____
PQA/QC Mgr Dispos Concur	Malinowski F	Date	12/08/06
QC Field Verification By	Phelps C	Date	01/18/06

Distribution

Cog Heitzenroeder P
Insp Chrzanowski


Proj. Doc Control (when closed)
 QC Files
 Malsbury J
 Boscoe J
 Sutton L
 Nelson B
 Reiersen W
 Williams m
 Lumberger J
 Tyrrell M
 Malinowski F
 Phelps C

A4 “gully” by Tee Radius




This photo shows the location - between Holes #86 to #94 on the side of the casting facing up on the shipping skid.

The next one shows a straight edge reference.



Note in both photos the shadow along the base of the tee. This is step, readily detected by hand, from the flat of the tee down toward the radius.

A4 "gully" by Tee Radius




More shots of the straight edge on the long and short legs of the tee.



The first photo shows a 5/32" gauge. The second is the required 1/8" radius gauge

A4 "gully" by Tee Radius

These photos show a short area, between holes #48 & #52 on the bottom side (as-shipped) of the casting, where the radius did not pass the gage check.



The first shows the required 1/8" gauge and the second shows the next size bigger 5/32" gauge.