PPPL NONCON	FORMANCE REPORT	NO: 3695 Ope	en Date	01/12/07	
Status	5 - Corrective Action Needed	Trend	01-	-Deviation From D	oc/Proc
-	VCSX	Divisi	on WBS	141	
-	/ENDOR				
Item Dwg/Part#	D-NCSX-MCF-001 Rev. 03	Procurement # S0	05242-F	Cos	t Center 9450 1*** 1404
RAP# 3209	Job Doc # S005242-F	Vendor Energ	jy Industrie	es of Ohio	
RAP Title NCSX -	Modular Coil Winding Forms				
HoldTag Appl	ied				
Nonconforming C	ondition (include requiren	ent(s) violated):			
werefound to exhibit	e magnetic permeability verifica a permeability above the maxim neability of any point in the wind es are attached.	um allowed. NCSX-CSPEC	C-141-03-1	1 paragraph 3.1.1	.5.1 states "the local
	_0 Sample Size elps C Valid * Repair* Use As Is*	ated By Malinowski F		Rejected Validatec	# Rejected I Date Rework
	ni be ground to remove the hig	r permeability containinat		lested. Jim Ginza	nowski will coordinate this work.
For rework or repair	of vendor supplied equipmen	ts, fill in information belo	ow:		Distribution
#Hours	\$Est Labor	\$G&A			Cog <u>Heitzenroeder P</u>
\$Material	\$Burden	=	\$1000	_	Insp Phelps C Proj. Doc Control (when
				_	- closed)
Disposition By	Chrzanowski J		Date	01/16/07	QC Files
Supervisor's Cond	cur Nelson B (RLM)		Date	01/16/07	Malsbury J
Eng. Dept. Head C			Date	01/16/07	Boscoe J Chrzanowski J
WCO/Other			Date		Sutton L
	<u>N/A</u>				Malinowski F – Nelson B
PQA/QC Mgr Disp QC Field Verificati	os Concur <u>Malinowski F</u>		Date	01/24/07	Reiersen W Williams M Tyrrell M

B3 high magnetic permeability areas NCR 1/11/07























