Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON E-Mail: NKHFlowen@aol.com

Part: SE141-115 / MODULAR COIL, TYPE B Revision: 8

Drawing ID: SE141-115

Reported By: MIKE GRIFFITH E-Mail: mGriffith@MajorTool.com

Problem: Sheet 5, zone D4.

8 of the 1.375 threaded holes on datum -E- are out of position by a 1/2 inch (holes 19 thru 26).

Proposed Disposition:

MTM RECOMMENDS REPAIRING HOLES PER ATTACHED REWORK PROPOSAL.

Number of additional pages: 2 Page Rework Proposal

Customer Disposition:	[] Use As Is	[] Rework	[] Repair	[] Scrap	[] Replace	
-----------------------	---------------	-----------	-----------	----------	------------	--

Major Tool Implemented By:	
----------------------------	--

Title:

Date:

/Open /WO:65708-2

n:\mtmapps\Mtnonc14.qrp

Major Tool and Machine, Inc. 1458 East 19th Street, Indianapolis, IN 46218-4289 Tel: 317-636-6433 Fax: 317-634-9420

Telephone: 216-496-2314 Fax: 216-328-2001

Customer P.O.: S005242-F/Ln:2 Serial No./Qty: B2

> Telephone: 317-636-6433 Fax: 317-634-9420



SE141-115 Type B2 Flange Hole Rework Proposal

Rework Proposal for Holes 19 thru 26:

•Oversize holes for a Ø2.50-6 UN insert.

•Inserts will be manufactured complete with the \emptyset 1.375-6 ID thread.

•For 5 Blind Holes: bottom out insert in hole (approx. 1.6' deep) and tack weld in 4 places on flange.

•For 3 Thru Holes: install insert and tack weld in 4 places on flange face and 4 places on back side of flange.

•All inserts will be faced off flush with Datum -E- flange.



