
Major Tool & Machine, Inc.

1458 East 19th Street
MTM N/C: 20487
Indianapolis, IN 46218-4289


Page: 1
Date: 09/18/06
User ID: GRIFFITH

Contact:	E ENERGY INDUSTRIES OF OHIO E NANCY HORTON E NKHFlowen@aol.com			Telephone: 216-496-2314 Fax: 216-328-2001		
Drawing ID:	SE141-115 / MODULAR COIL, TYPE B SE141-102 Revision: 3 1-Type:W: 65708/1.0 Sub: 1			Customer P.O.: S005242-F/Ln:1 Serial No./Qty: B1		
	MIKE GRIFFITH mGriffith@MajorTool.com	Telephone: 317-636-6433 Fax: 317-634-9420				
Problem: Proposed Dispo	oblem: Two areas are nonconforming per NCSX-CSPEC-141-03 section 4.2.6. (see attachment for details) 1) The top right corner from 3" across to 4.3" down defines an area that exceeds the limit of .015" gap up to 1/8" deep. The max. gap is at the top where a .032" shim will start. 2) The area bordered by the red lines in the thick section of the T will allow for a .005" shim to pass completely thru. The specification requires the cumulative gap to be <.005".					
MTM proposes that Gap deviation be accepted as is. All sharp edges from mismatch have been blended smooth.						
Number of additional pages: 2 page summary Customer Disposition: [] Use As Is [] Rework [] Repair [] Scrap [] Replace						
Major Tool Implemented By:			Т	itle <u>:</u>	Date:	

NC20487 Poloidal Break Gap – SE141-115 B1




NC20487 Poloidal Break Gap – SE141-115 B1



View to the left is looking down on the datum E flange. The gap between G11 and flange face is visible on the left side of the break shim.







Top-right shows a .032" shim starting (2.5" from inner casting wall.

Top-left shows a .015" shim starting (3.0" from inner casting wall.

Bottom-left shows a .015" starting 4.3" from datum E face.