

Princeton University

**Plasma Physics Laboratory**  
James Forrestal Campus  
P.O. Box CN17  
Princeton, N.J. 08543

8 December 2006

Ms. Nancy Horton  
Energy Industries of Ohio  
6100 Oak Tree Boulevard, Suite 200  
Independence, Ohio 44131

**SUBJECT: Subcontract S005242-F for NCSX Modular Coil Winding Forms  
PPPL Non-Conformance Report (NCR) 3684**


Dear Ms. Horton:

Attached *for information* is dispositioned Princeton Plasma Physics Laboratory (PPPL) Non-Conformance Report 3684, dated 30 November 2006 titled NCSX – Modular Coil Winding Forms.

The “corrective action” required by the NCR will be performed by PPPL. Subject Report is provided to EIO for information only.

If there are any comments pertaining to this matter I may be contacted at (609) 243-2441 and by e-mail [lsutton@pppl.gov](mailto:lsutton@pppl.gov).

Regards,



Larry L. Sutton  
Senior Subcontract Administrator

Attachment

<b>Status</b>	5 - Corrective Action Needed	<b>Trend</b>	01-Deviation From Doc/Proc
<b>Department</b>	NCSX	<b>Division</b>	WBS 141
<b>Source/Org</b>	VENDOR		
<b>Item Dwg/Part#</b>	SE141-114, r8 - MCWF A-4	<b>Procurement #</b>	S005242-F
		<b>Cost Center</b>	9450 1*** 1404
<b>RAP#</b>	3209	<b>Job Doc #</b>	S005242-F
		<b>Vendor</b>	Energy Industries of Ohio
<b>RAP Title</b>	NCSX - Modular Coil Winding Forms		

HoldTag Applied

**Nonconforming Condition (include requirement(s) violated):**

MCWF A-4 shows the following conditions (photos attached) exceeding the tolerances of SE141-114, R8:  
 1) Between Holes #86 to #94 the legs of the Tee (septum) have a step down area that dips, on the long leg, .008" to .028" from the flat portion of the leg. MTM's measurements of the long leg in this area show it .002" to .003" above nominal, so the "gully" ranges from .010", just at the upper limit of the tolerance of .020" profile equally distributed bilaterally (+/- .010"), to as much as .020" below that tolerance. There is a similar, though more shallow, "gully" on the short leg.  
 2) Between Holes #48 & #52 the radius between the long and short legs of the Tee exceeds the specified .11" +/- .01".

<b>Lot Size Recd</b>	1	<b>Sample Size Insp</b>	1	<input type="checkbox"/> Lot Rejected	<b># Rejected</b>	1
<b>Reported By</b>	Phelps C	<b>Validated By</b>	Malinowski F	<b>Validated Date</b>	11/27/06	

**Disposition:** Rework\*  Repair\*  Use As Is\*  Return To Vendor\*  Scrap\*  Rework

The "gully" areas should be filled in with CTD 540 epoxy / glass bead to provide an even surface and support for the winding. This condition will be discussed with EIO/MTM during the next Quality call to avoid this condition with future castings.

**For rework or repair of vendor supplied equipments, fill in information below:**

<b>#Hours</b>	_____	<b>\$Est Labor</b>	_____	<b>\$G&amp;A</b>	_____
<b>\$Material</b>	_____	<b>\$Burden</b>	_____	<b>\$Total</b>	\$425
<b>Disposition By</b>	Heitzenroeder P	<b>Date</b>	11/30/06		
<b>Supervisor's Concur</b>	Nelson B	<b>Date</b>	11/30/06		
<b>Eng. Dept. Head Concur</b>	Williams M	<b>Date</b>	12/01/06		
<b>WCO/Other</b>	N/A	<b>Date</b>	_____		
<b>PQA/QC Mgr Dispos Concur</b>	Malinowski F	<b>Date</b>	12/08/06		
<b>QC Field Verification By</b>	_____	<b>Date</b>	_____		

**Distribution**

**Cog** Heitzenroeder P  
**Insp** Chrzanowski


Proj. Doc Control (when closed)  
 QC Files  
 Malsbury J  
 Boscoe J  
 Sutton L  
 Nelson B  
 Reiersen W  
 Williams m  
 Lumberger J  
 Tyrrell M  
 Malinowski F  
 Phelps C

## A4 “gully” by Tee Radius




This photo shows the location - between Holes #86 to #94 on the side of the casting facing up on the shipping skid.

The next one shows a straight edge reference.



Note in both photos the shadow along the base of the tee. This is step, readily detected by hand, from the flat of the tee down toward the radius.

## A4 "gully" by Tee Radius




More shots of the straight edge on the long and short legs of the tee.



The first photo shows a 5/32" gauge. The second is the required 1/8" radius gauge

### A4 “gully” by Tee Radius

These photos show a short area, between holes #48 & #52 on the bottom side (as-shipped) of the casting, where the radius did not pass the gage check.



The first shows the required 1/8" gage and the second shows the next size bigger 5/32" gage.