Customer: PRINCETON PLASMA PHYSICS LABContact: Mike ViolaTelephone: 609-243-3655E-Mail: mviola@pppl.govFax: 609-243-3248Part: SE120-004-52 / O-RING, METAL, HELICOFLEX TYPEDrawing ID: SE120-004Revision: 1Customer P.O.: S005243-F/Ln:8Qty: 2 setsReported By: DOUG MCCORKLEE-Mail: dMcCorkle@MajorTool.comFax: 317-636-6433Fax: 317-634-9420

Problem: BOTH LOT 8 AND 9 OUTER HELICOFLEX METAL SEALS ARE TOO SMALL TO ALLOW FOR PROPER FIT OF RETAINING STRIP. ACTUAL AMOUNT TOO SMALL IS UNKNOWN, VISUALLY APPEARS TO BE .120 TOO SMALL. IN OTHER WORDS THE OD OF SEAL RETAINER WOULD NEED .100 OFF ALL WAY AROUND TO MAKE WORK.

LOT 9 HAS MINOR DAMAGE TO SEALING FACE ON CUSTOMER SUPPLIED SEAL.

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of addi	tional pages:					
Customer Disposition: [] Use As Is		[] Rework	[] Repair	[] Scrap	[] Replace	
Technical Contac	t Annroval.		,	Title:		Date:
Buye			Title <u>:</u>		Date:	
Major Tool Implemented By:				Title <u>:</u>		Date:

Major Tool and Machine, Inc. 1458 East 19th Street, Indianapolis, IN 46218-4289 Tel: 317-636-6433 Fax: 317-634-9420

Nonconformance Report: Major Tool NC19254

This is for SE120-004-52 / O-RING, METAL, HELICOFLEX TYPE

Problem:

BOTH LOT 8 AND 9 OUTER HELICOFLEX METAL SEALS ARE TOO SMALL TO ALLOW FOR PROPER FIT OF RETAINING STRIP. ACTUAL AMOUNT TOO SMALL IS UNKNOWN, VISUALLY APPEARS TO BE .120 TOO SMALL. IN OTHER WORDS THE OD OF SEAL RETAINER WOULD NEED .100 OFF ALL WAY AROUND TO MAKE WORK.

LOT 9 HAS MINOR DAMAGE TO SEALING FACE ON CUSTOMER SUPPLIED SEAL.

Doug McCorkle

Project Disposition:

Rework first retainer set as desired - retainer strip radii may be cut off to allow for circumferential difference or tongue depressors may be used in place of seal retainer to hold seals in place during assembly.

Second and third set may be left per print.

Approvals:

Procurement Technical Representative

Responsible Line Manager:

Project Quality Assurance: