PPPL NONCOM	NFORMANCE REPO	ORT NO:	3659	Open D)ate	07/05/06	Rev #:	<mark>2,3/13/2007</mark>		
Status	2 - Disposition Needed	9-Closed	/	Trend	01-D	eviation From	n Doc/Proc			
Department	NCSX			Division	NCSX	(Project				
Source/Org	FABRICATION, OPERATIC	NS & MAINTE	NANCE							
Item Dwg/Part#	D-NCSX-MCF-001 Rev. 02	Procu	irement #	D-NCS>	X-MCF-	001	Cost Center	9450-1***-1451		
RAP# 3207	Job Doc # D-NCSX	-MCF-001	Vendor							
RAP Title Modular Coil Fabrication - Winding Form Preparation Activities										
HoldTag Applied										
Nonconforming Condition (include requirement(s) violated):										
The lead block mounts for the A1 modular coil are beyond the maximum magnetic permeability of 1.02 Mu as stated in NCSX-ASPEC-GRD-04 paragraph 3.3.1.1. These parts were manufactured by PPPL and made from 316 stainless steel. The remaining A type lead block mounts have yet to made and will most likely have a similar amount of magnetic permeability. At the time of this report six pieces have been made. Inside diameter (machined threads) = greater than 1.3 Mu and less than 1.7 Mu NCR #3628 was written on the C type lead block mounts and accepted as is with a magnetic permeability of greater than 1.02 Mu and less than 1.7 Mu NCR #3628 was written on the C type lead block mounts for the A2 & A3 coils are above the maximum magnetic permeability of 1.02 Mu. A2 = >1.2 Mu <1.8 Mu, A3 = >1.3 Mu <1.7 Mu. With three of the six coils having this condition it will most likely affect the A4 thru A6 coils as well. When dispositioning this NCR please consider this issue for all of the A coils. Rev 2: A4 lead block mounts range from >1.3 to <1.5 Mu and are installed, A5 and A6 lead block mounts range from >1.4 to <1.5 Mu and are not installed. Lot Rejected <u>6</u> Sample Size Insp <u>4</u> Lot Rejected <u>6</u> Reported By Phelps C Validated By Boscoe J Validated Date <u>3/14/07</u> Disposition: Rework*_ Repair*_ Use As Is*_ Return To Vendor*_ Scrap* NOTE, Rev 0: Awaiting test results from outside laboratory to determine whether the permeability of the 316ss parts can be used as is without further work. 12/08/06: Status unchanged.										
For rework or repai	ir of vendor supplied equi	nments fill ir	n informati	on below.			Distrib	ution		
		•						J. Chrzanowski		
#Hours	\$Est La			G&A				Phelps C		
\$Material	\$Burde	en	\$	Total		_	Proj. Do closed)	oc Control (when		
Disposition By					Date		QC Files	5		
Supervisor's Co	ncur			[Date		Malsbur Boscoe	·		
Eng. Dept. Head	Concur	\checkmark	-	[Date		T. Meig			
WCO/Other				r	Date		Dudek I	-		
				•			Reierse			
							Tyrrell N			
PQA/QC Mgr Dis	pos Concur				Date					
QC Field Verifica	tion By				Date		-			
/							\sim			

Disposition:	Rework	Repair	Use As Is	Return to Vendor	Scrap				
		Q							
For rework or repair of vendor supplied equipment, fill in information below:									
# Hour	'S	\$ Est Lab	or	\$ G&A					
\$ Mate	rial	\$ Burden		\$ Total					
Disposition b	у								
Supervisor's	Concurrence								
Eng. Dept. He	ead Concurren	ce							
Other (i.e., W	CO/FPE) Conc	urrence							
PQA/QC Mgr	Disposition Co	oncurrence							
QA Field Veri	fication by								
					n)				
					p. 2				