Quality Impact: (If none, so state): NONE

State Requirement Deviation is Requested For: (Specification, MIT/QA Plan, SOW, drawing, etc.): SE141-114

Full Description of the Deviation Requested: (Use continuation pages, e-mails, letter, sketches, etc. as needed and include amplifying information as appropriate to support deviation request.):

Major Tool noted casting interference at the bolt locations shown in the attached figures for the Type A1 casting. For the A1 casting details shown on SE141-114, the two holes will be changed from clearance holes to tapped holes as shown n Attachment (1) in which MTM describes the areas of interference. This casting interference is similar to what was noted on the Type C winding forms, but more severe in these areas. PPPL letter (L. Sutton to N. Horton) dated April 20, 2006, authorized this change for the A1 casting as shown in Attachment (2).


In response to this, NCSX reviewed remaining flange holes all the Type A castings and developed the concept shown on Attachment (3) in which a number of the clearance holes have been changed to tapped holes. All Type A MCWFs shall be manufactured per this.

Attachments:

- (1) Pictures showing interference details.
- (2) Annotated SE141-114 all the proposed changes to the Type A1 MCWF.
- (3) Proposed changes to all Type A MCWfS


Initiator Signature: Mike Griffith/Phil Heitzenroeder


Attachment (1) Type A MCWF Interferences




Relief area cut into cast wall

The pictures below illustrate how much casting wall interference there will be on the type A casting. The current machining models for all three winding forms have this interference problem to some degree. The models have a 3" counterbore that extends .75" from the face and the remainder of the feature is a 1.5" radius (see below). This is why Major Tool had to perform the grinding around the counterbores on C4 in order to get the 3" diameter gage to fit.








Attachment (2) Proposed Resolution to Type A MCWFs


SE141-114 MCWF TYPE-A1

Proposed change to 1.885 thru holes





Mike Griffith Page 1 of 1 5/9/2006







Attachment (3)
Definition of Holes to be Modified for ALL Type A MCWFs
(Reference: D.Williamson e-mail of May 4, 2006)









\

NCSX RFD	Number: 14-018		RFD Description: Type A MCWF Flange Hole Modifications				
IPart III			Tiole Widdiffications				
RLM: Brad Nelson		Organization: ORNL					
Impact on Interfaces with Other WBS Elements/Items: (If none, so state): NONE							
RLM Recommendation:							
Additional remarks:							
This RFD also includes a modification by the NCSX Project for all the Type A MCWF flange holes. The minimum stud clearance required behind the tapped holes shall not be less than ½" to ensure full thread engagement.							
These modifications will be incorporated in a future revision to this drawing. In the interim that "stamp" process will be used to annotate SE141-114.							
Does this Change Impact Material Already Procured or Parts/Assemblies Already Assembled/Manufactured using this Material: \boxtimes Yes \square No							
If "Yes", what is the recommended disposition of this material/part/assembly? A1 Casting will be accepted "as is" with the exception of the two holes shown.							
RLM Signature:							
Project Disposition:							
Approved. No ECP required.							
NCSX Systems Engineering Support Manager Approved. ECP will be assigned and processed.							
☐ Not Approved. Reason(s) for disapproval:							