

# EVERSON TESLA INCORPORATED

NCR # SC08013

## NON CONFORMANCE REPORT

Part No: 53028 Description: Princeton Coil #10 PO/WO No: 939  
 Supplier: ETI Date Rec'd: 3/19/08 Date Insp: 3/19/08  
 Prepared By: R. Brown Qty Rec'd: 1 Qty NC: 1

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	PPPL #SE131-003 ET #53028				Machine operator crashed tool holder into top wedge of Coil #10 prior to machining. See photos attached. after final machining.
	Coil #10				

Supplier Responsible?  Yes  No

Corrective Action Req'd?  Yes  No

Disposition: indicate qty

UAI	RTV	Screen
Rework	Scrap	Repair

Customer Approval Req'd:  Yes  No

Customer Signature: Michael Kalish 3/27/08 P. Platzner

Remarks: EXTRA CARE TO BE TAKEN TO VERIFY THAT PART DID NOT SHIFT. FINAL MEASUREMENTS TO VERIFY FINAL DIMENSIONS. REVIEW WITH OPERATOR HOW THIS HAPPENED TO ENSURE NO REPEAT.

Approval:

Department	Signature	Date
Engineering	<u>[Signature]</u>	<u>3/24/08</u>
Quality Assurance		

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: \_\_\_\_\_ Date: \_\_\_\_\_