PPPL NONCONF	ORMANC	E REPORT	NO: 368	5 Open	Date	11/30/06			
_	9 - Closed NCR				01-De	01-Deviation From Doc/Proc			
_	ICSX			_ Division	WBS	141			
_	ENDOR								
Item Dwg/Part# <u>D</u>	-NCSX-MCF-00	01 Rev. 03	Procurement #	nt # S0052	<b>\$</b> 5005242-F		Cost Center	9450 1*** 1404	
RAP# 3209	Job Doc#	S005242-F	Vend	lor Energy Ir	ndustrie	s of Ohio			
RAP Title NCSX - N	Modular Coil W	inding Forms							
☐ HoldTag Appli	ed								
Nonconforming Co	ondition (inc	clude require	ment(s) violat	ed):					
the inside of one of the Representative picture  Lot Size Recd				r areas were to		as cast surf	aces. # Reje	<b>cted</b> 0	
_	elps C	•	-	——		·	dated Date	11/27/06	
Disposition: Rework	•				p*			Chrzanowski J	
The lip found on the ir	nside of one of	the lead block	slots was remov	ed (see attach	ed emai	I from J. Ch	rzanowski). <b>y</b>		
For rework or repair of vendor supplied equipments, fill in information bel							<u>Distri</u>	<u>Distribution</u>	
#Hours		\$Est Labor		\$G&A		_	Cog	<u>Heitzenroeder P</u> <u>Chrzanowski J</u>	
\$Material		\$Burden		\$Total	\$700	_	Insp Proj. [ ————————————————————————————————————	Ooc Control (when	
Disposition By		Chrzanowski J			Date	01/19/07	QC File	es	
Supervisor's Conc	ur	Nelson B (RLM	1)		Date	01/19/07	Malsbi Bosco	•	
Eng. Dept. Head Co	Concur Williams M				Date	01/29/07	Nelsor	Nelson B	
WCO/Other		N/A			Date		Reiers Williar		
PQA/QC Mgr Dispo							Suttor Lumbe	ı L	
QC Field Verification		<u>Malinowski</u>	F		Date Date	01/01/01	Tyrrell Malinc Phelps	l M owski F	

A4 High Magnetic Permeability Areas and Lead Block Slot Lip NCR 11/30/06






Page 1 of 4



Page 2 of 4







Lead Block Slot Lip



Page 4 of 4