

Rev 9-a: RFD-14-023R1 stated that the tapped and drilled holes in the VV support bosses (pads) as shown in the drawings should be provided to the maximum extent possible, given the undersize condition of some of the pads. *To help in this regard, MTM was requested to offset the hole pattern relative to the cast pads as necessary to permit more (or all) of the tapped holes in the pads to be provided.* NCSX will weld mounting studs as needed. **This is considered a relatively minor change and a drawing change will not be required.**

(See RFD-14-023R1 for details)

