National Compact Stellarator Experiment

NCSX

QUALITY ASSURANCE PLAN

NCSX-PLAN-QAP-01

March 22, 2006

Judith Malsbury Physic N = Judith Malsbury PPC, OU = Ouality Assurance PPC, OU = Ouality Assurance PPC, OU = Ouality Assurance Passor: 1 and the author of this document Date: 2006.03.22 13:58:38 - 06'00'

Prepared by:

Judith Malsbury, NCSX Quality Assurance

Concurrence by:

John W. Dignally segned by John W Ardenson DP, Or J. John W Ardenson Anderson DP, Or J. John W Ardenson C J. J. S. O. = ESH and Inhabituctive Support. (J.J. Department Head Department Department Support. (J.J. Department Head Department Department Support. (J.J. Department Head Departm

Jim Lyon C = Us, O = ORNL, OU = Fusion Energy Dhis Date: 2006.03.22 14:47:14 -05'00

. Reason: I concur Date: 2006.03.30 10:55:51 -05'00'

J. F. Lyon, Deputy Proj. Mgr., ORNL

Wayne Reiersen DN: CN = W

W. Reiersen, NCSX

Hutch Neilson DN: CN = Hutch Neilson CO = PPPL Date: 2006.03.30 08:57:35 -05'00

G. H. Neilson, Project Mgr

Engineering

Digitally signed by Mike Williams DN: cn=Mike Williams, c=US, o=PPPL, ou=Engineering, email=williams@pppl. Mike Williams gov Date: 2006.03.30 12:25:48 -05'00' M. Williams, Head, PPPL Engineering

Approved by:

Dr. R. J. Goldston, PPPL Director

^{*} The PPPL QA Plan, EQP-004, requires that project specific QA Plans have the concurrence of the Head, Quality Assurance (QA). Since the Head, QA is also the preparer of the NCSX QA Plan, this concurrence signature is elevated one level in the PPPL organization.

RECORD OF REVISIONS

Revision	Date	Resp. Ind.	Description of Change
0	11/02	Malsbury	Initial Release.
1	3/06	Malsbury	Updated to reflect changes in project plans and procedure and the project moving beyond the design stage.

1.0 PURPOSE

The National Compact Stellarator Experiment (NCSX) is a proof-of-principle-scale facility for studying the physics of compact stellarators, an innovative fusion confinement concept. The facility will include the stellarator device and ancillary support systems. NCSX is a joint project of the Oak Ridge National Laboratory (ORNL) Fusion Energy Division and the Princeton Plasma Physics Laboratory (PPPL) Advanced Projects Department.

This document defines the Quality Assurance Plan for NCSX. It is effective from the date of final signatures through first plasma. This Plan satisfies the requirements of the most recent version of DOE O 414.1, Quality Assurance.

2.0 RELATED DOCUMENTS

The following are related documents (current versions):

- DOE O 414.1, Quality Assurance
- DOE O 413.3, Program and Project Management for the Acquisition of Capital Assets
- The PPPL Institutional Quality Assurance Plan (IQAP), EQP-004
- The ORNL Fusion Energy Division Management and Integrated Safety Management System Plan, QAP-X-FE-001, Rev. 0, February 2002
- Plans and procedures as indicated in the Appendix

3.0 THE NCSX QUALITY ASSURANCE PLAN

Quality assurance requirements for non-nuclear facilities are described in the DOE order on quality assurance, DOE O 414.1. The PPPL Institutional Quality Assurance Plan referenced above has been approved by DOE for non-nuclear work performed at PPPL. The NCSX Quality Assurance Plan described in this document integrates the PPPL Quality Assurance Plan with implementing PPPL and ORNL plans and procedures to assure that an appropriate quality assurance program exists for NCSX. NCSX plans and PPPL procedures will be used for all project work activities, independent of the site at which the work will be performed, unless noted otherwise in the appendix.

The Appendix to this Plan contains the following:

• The quality requirements from DOE O 414.1

• The list of plans, policies, and procedures applicable to work performed for NCSX.

4.0 ASSUMPTIONS

This Quality Assurance Plan makes the following assumptions:

- As documented in the Project Execution Plan, ORNL is responsible for the design of all WBS 1 systems. PPPL personnel will support ORNL in the design of WBS 1 systems. WBS 1 systems are the stellarator core systems and include the plasma facing components, vacuum vessel and in-vessel structures, TF and PF coil systems, cryostat, machine support structure, modular coil systems, and trim coil systems. Responsibilities include developing designs, generating drawings suitable for fabrication, and specifying additional procurement requirements, such as statements of work or specifications. In support of this effort, fabrication of prototypes may be performed by ORNL.
- PPPL is responsible for all remaining systems and the final assembly and installation of NCSX.
- With minor exceptions, all procurements of hardware are the responsibility of PPPL. However, either Laboratory may procure services, such as analysis or manufacturing studies.

These assumptions impact the choice of procedures invoked on behalf of the NCSX project.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

 1.0, Management /Program (a) A written QAP must be developed, implemented, and maintained. (b) The QAP must describe the organizational structure, functional responsibilities, levels of authority, and interfaces for those managing, performing, and assessing the work. (c) The QAP must describe the management processes, including planning, scheduling, and resource considerations. 	NCSX Project Execution Plan NCSX Quality Assurance Plan (this plan)
 2.0, Management /Personnel Training and Qualification (a) Personnel must be trained and qualified to ensure they are capable of performing their assigned work. (b) Personnel must be provided continuing training to ensure that job proficiency is maintained. 	Design, Fabrication, and Construction Activities: NCSX Training Plan, NCSX-PLAN-TRNG
 3.0, Management /Quality Improvement (a) Processes to detect and prevent quality problems must be established and implemented. (b) Items, services, and processes that do not meet established requirements must be identified, controlled, and corrected according to the importance of the problem and the work affected. Correction must include identifying the causes of problems and working to prevent recurrence. (c) Item characteristics, process implementation, and other quality-related information must be reviewed and the data analyzed to identify items, services, and processes needing improvement. 	PPPL QA-005, Control of Nonconformances PPPL QA-012, Corrective Action Request PPPL QA-017, PPPL Tracking and Trending System PPPL QA-019, Root Cause Analysis

* See <u>http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm</u> for NCSX Plans, <u>http://www.pppl.gov/eshis/procedures.html</u> for PPPL procedures, <u>http://www.pppl.gov/eshis/ESHD_MANUAL/sm.html</u> for the PPPL ES&HD 5008 Manual. and <u>http://oorm-1-priv.pppl.gov/users/pro/policies/default.htm</u> for the PPPL Procurement Manual.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

4.0, Management /Documents and Records	NCSX Documents and Records Plan, NCSX-PLAN-DOC
(a) Documents must be prepared, reviewed, approved, issued, used, and revised to	NCSX Data Management Plan, NCSX-PLAN-DMP
prescribe processes, specify requirements, or	
establish design. (b) Records must be specified, prepared,	NCSX Interface Control Management Plan, NCSX-PLAN- ICMP
reviewed, approved, and maintained.	
	NCSX Configuration Management Plan, NCSX-PLAN-CMP
	PPPL ENG-010, Control of Drawings, Software, and Firmware
	NCSX Procedure-007, NCSX Electronic Model and Drawing/INTRALINK Processes
	NCSX procedure-006, Control of NCSX Supplier and In-House Fabrication Information

* See http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm for NCSX Plans, http://www.pppl.gov/eshis/procedures.html for PPPL procedures, http://www.pppl.gov/eshis/ESHD_MANUAL/sm.html for the PPPL ES&HD 5008 Manual. and http://oorm-1-priv.pppl.gov/eshis/procedures.html for the PPPL Procurement Manual.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

5.0, Performance /Work Processes	Most of the work, excluding design, will be performed at PPPL.
(a) Work must be performed to established	For these work activities, normal PPPL procedures will be followed. Typical ones are:
technical standards and administrative controls, using approved instructions, procedures, or other approved means.	ENG-002, Control of Measuring and Test (MTE) Equipment
(b) Items must be identified and controlled to assure their proper use.	ENG-010, Control of Drawings, Software, and Firmware
(c) Items must be maintained to prevent their damage, loss, or deterioration.	ENG-012, Identification & Control of Items
(d) Equipment used for process monitoring or data collection must be calibrated and	ENG-014, Hydrostatic and Pneumatic Testing
maintained.	ENG-016, PPPL Preventive Maintenance Program
	ENG-021, Hoisting and Rigging Program
	ENG-030, PPPL Technical Procedures for Experimental Facilities
	ENG-032, Work Planning Procedure
	ENG-037, General Welding and Brazing Requirements
	PPPL Engineering Standards
	ES&H Manual, ES&HD 5008
	ESH-004, Job Hazards Analysis
	ESH-016, Control of Hazardous/Energy Sources – Safing/ Lockout/Tagout
	Field work performed at ORNL will follow ORNL procedures.
	Specific to NCSX:
	NCSX procedure-004, NCSX Work Authorization Process

* See <u>http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm</u> for NCSX Plans, <u>http://www.pppl.gov/eshis/procedures.html</u> for PPPL procedures, <u>http://www.pppl.gov/eshis/ESHD_MANUAL/sm.html</u> for the PPPL ES&HD 5008 Manual. and <u>http://oorm-1-priv.pppl.gov/users/pro/policies/default.htm</u> for the PPPL Procurement Manual.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

6.0,	Performance /Design	
<i>,</i>	e	NCSX Interface Control Management Plan, NCSX-PLAN-
(a)	Items and processes must be designed using	ICMP
	sound engineering/scientific principles and	
	appropriate standards.	PPPL ENG-010, Control of Drawings, Software, and Firmware
	Design work, including changes, must	
	incorporate applicable requirements and	PPPL ENG-032, Work Planning Procedure
	design bases.	
	Design interfaces must be identified and	PPPL ENG-033, Design Verification
	controlled.	
	The adequacy of design products must be	NCSX Reliability, Availability, and Maintainability Plan, NCSX-PLAN-RAM
	verified or validated by individuals or groups other than those who performed the	NC5A-PLAN-RAM
	work.	PPPL Engineering Standards
	Verification and validation work must be	TTTE Engineering Standards
· · ·	completed before approval and	NCSX Materials Properties
	implementation of the design.	(http://ncsx.pppl.gov/NCSX Engineering/Materials/index Ma
	1	terials.htm)
		NCSX Vacuum Mterials Committee and results
		(http://ncsx.pppl.gov/NCSX Engineering/Materials/Vacuum
		Materials/index VacuumMaterials.htm)
		NCSX Design Criteria
		(http://ncsx.pppl.gov/NCSX_Engineering/Design_Criteria/ind
		ex_design_criteria.htm)
		NCSX procedure-009, Request for Deviation Process
		NCSA procedure-009, Request for Deviation riocess
		NCSX procedure 010, NCSX Design Review Processes
		•

* See http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm for NCSX Plans, http://www.pppl.gov/eshis/procedures.html for PPPL procedures, http://www.pppl.gov/eshis/ESHD_MANUAL/sm.html for the PPPL ES&HD 5008 Manual. and http://oorm-1-priv.pppl.gov/eshis/procedures.html for the PPPL Procurement Manual.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

7.0, Performance /Procurement	Most of the procurements will be performed by PPPL under the PPPL systems listed below:
 (a) Procured items and services must meet established requirements and perform as specified. (b) Prospective suppliers must be evaluated and selected on the basis of specified criteria. (c) Processes to ensure that approved suppliers continue to provide acceptable items and services must be established and implemented. 	 PPPL Procurement Manual QA-003, Procurement Quality Assurance QA-009, DCMAO Vendor Survey/Surveillance Delegation QA-020, Identifying and Dispositioning Suspect Parts ENG-006, Review and Approval of Specifications & Statements of Work ENG-012, Identification & Control of Items 36.003, Subcontract Proposal Evaluation Board (SPEB) Policy NCSX_PROC_006, Control of NCSX Supplier nad In-House Fabrication Information A limited number of procurements will be performed by ORNL
 8.0, Performance /Inspection and Acceptance Testing (a) Inspection and testing of specified items, services, and processes must be conducted using established acceptance and performance criteria. (b) Equipment used for inspections and tests must be calibrated and maintained. 	 under the system described by the ORNL Management System Description - Acquisition Management. NCSX Test and Evaluation Plan, NCSX-PLAN-TEP QA-004, PPPL Site Inspection Program QA-009, DCMAO Vendor Survey/Surveillance Delegation ENG-002, Control of Measuring and Test (MTE) Equipment ENG-014, Hydrostatic and Pneumatic Testing ORNL personnel working at ORNL and performing inspection and acceptance testing will follow ORNL procedures.
 9.0, Assessment /Management Assessment (a) Managers must assess their management processes. (b) Problems that hinder the organization from achieving its objectives must be identified and corrected. 	ORNL FED Self-Assessment Plan P-026, Assessment and Oversight

^{*} See <u>http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm</u> for NCSX Plans, <u>http://www.pppl.gov/eshis/procedures.html</u> for PPPL procedures, <u>http://www.pppl.gov/eshis/ESHD_MANUAL/sm.html</u> for the PPPL ES&HD 5008 Manual. and <u>http://oorm-1-priv.pppl.gov/users/pro/policies/default.htm</u> for the PPPL Procurement Manual.

List of Implementing Plans and Procedures for the NCSX Project

Requirement from DOE O 414.1

Applicable Plans and Procedures

 10.0, Assessment /Independent Assessment (a) Independent assessments must be planned and conducted to measure item and service quality, to measure the adequacy of work performance, and to promote improvement. (b) The group performing independent assessments must have sufficient authority and freedom from the line to carry out its responsibilities. (c) Persons conducting independent assessments must be technically qualified and knowledgeable in the areas assessed. 	QA-002, PPPL Audit Program
 11.0 Suspect/Counterfeit Items (a) An S/CI prevention process must be developed and implmeneted as part of the contractor's QAP and must be commensurate with the facility/activity hazards and mission impact The QAP must address the following elements for S/CI prevention: preventing the introduction and use of S/CIs trhough engineering involvement, training on S/CI processes and controls, Identifying and dispositioning S/CIs onsite, restricting S/CIs to those found acceptable via engineering analysis and formal disposition processes, disseminating and using the most accurate and up-do-date information on S/CIs, and identifying the management point of contract for S/CI information notices. 	P-041, Suspect Parts QA-020, Identifying and Dispositioning Suspect Parts

* See http://ncsx.pppl.gov/SystemsEngineering/Plans_Procedures/NCSX_Mgmt_Plans.htm for NCSX Plans, http://www.pppl.gov/eshis/procedures.html for PPPL procedures, http://www.pppl.gov/eshis/procedures.html for the PPPL ES&HD 5008 Manual. and http://oorm-1-priv.pppl.gov/eshis/procedures.html for the PPPL Procurement Manual.