
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: LARRY SUTTON
E-Mail: S-04286-F

Telephone: 609-243-2441
Fax: 609-243-2021

Part: /

Drawing ID: SE122-007

Revision: 2

Customer P.O.: S005243-F/Ln:1
Serial No./Qty:

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: The positions of ports 17 a and b and 18 a and b are out of tolerance.

Port 17a checks 1.351 position and the face checks -0.238 / -0.172..

Port 17b checks 1.163 position and the face checks -0.293 / -0.255.

Port 18a checks 1.083 position and the face checks +0.068 / +0.134.

Port 18b checks 1.077 position and the face checks -0.095 / -0.030.

Proposed Disposition:

Corresponding point cloud inspection data uploaded to PPPL ftp site 04May2006.

Number of additional pages: _____

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____

Nonconformance Report: 19612 Rev.A

Problem: The positions of ports 17 a and b and 18 a and b are out of tolerance.

Port 17a checks 1.351 position and the face checks -0.238 / -0.172..

Port 17b checks 1.163 position and the face checks -0.293 / -0.255.

Port 18a checks 1.083 position and the face checks +0.068 / +0.134.

Port 18b checks 1.077 position and the face checks -0.095 / -0.030

Project Disposition:

Use As-is

Approvals:

Procurement Technical Representative

Responsible Line Manager: