Open Date 03/27/06 PPPL NONCONFORMANCE REPORT NO: 3641 Status 2 - Disposition Needed 01-Deviation From Doc/Proc Trend Department **NCSX** NCSX Project Division Source/Org FABRICATION, OPERATIONS & MAINTENANCE Item Dwg/Part# N/A Procurement # D-NCSX-MCF-004-00 **Cost Center** RAP# 3234 Job Doc # D-NCSX-MCF-004 Vendor RAP Title Modular Coil Fabrication - Post VPI Activities HoldTag Applied Nonconforming Condition (include requirement(s) violated): C1 MCWF - There is a coil winding clamp stud manually welded to the top of the polodial break shim on the C1 modular coil that exhibits a permeability >1.2, <1.8. Maximum allowable magnetic permeability is 1.02 per NCSX-ASPEC-GRD-04 paragraph 3.3.1.1. This stud was broken off after VPI operations in an attempt to remove it from the assembly but some weld material remains which is why permeability is beyond the allowable limit. Sample Size Insp 0 _ Lot Size Recd 0 Lot Rejected # Rejected 0 Validated Date 03/27/06 Reported By Chrzanowski J Validated By Phelps C Disposition: Rework*__ Repair*__ Use As Is*__ Return To Vendor* Scrap* For rework or repair of vendor supplied equipments, fill in information below: Distribution Cog J. Chrzanowski \$G&A #Hours \$Est Labor Insp C. Phelps \$Burden ____ \$Total \$Material Proj. Doc Control (when closed) Date QC Files Disposition By Malsbury J Date Supervisor's Concur Boscoe J T. Meighan Date Eng. Dept. Head Concur Heitzenroeder P WCO/Other Date Reiersen W Dudek L Williams M Nelson B PQA/QC Mgr Dispos Concur Date Tyrrell M QC Field Verification By Date