

PPPL NONCONFORMANCE REPORT NO:3666Open Date08/29/06

Status	5 - Corrective Action Needed	Trend	06-Workmanship/Needs Repair		
Department	NCSX	Division	NCSX Project		
Source/Org	FABRICATION, OPERATIONS & MAINTENANCE				
Item Dwg/Part#	N/A	Procurement #	D-NCSX-MCF-002	Cost Center	
RAP#	3210	Job Doc #	D-NCSX-MCF-002	Vendor	
RAP TitleModular Coil Fabrication Winding Station Activities					
<input type="checkbox"/> HoldTag Applied					

**Nonconforming Condition (include requirement(s) violated):**  
MCWF C5, While preparing the conductors for final termination on the C5 modular coil the A1 conductor was inadvertently cut two inches (2") too short.

Lot Size Recd	0	Sample Size Insp	0	<input type="checkbox"/> Lot Rejected	# Rejected	0
Reported By	Chrzanowski J	Validated By		Validated Date		
Disposition: Rework*__ Repair*__ Use As Is*__ Return To Vendor*__ Scrap*__						Rework

For rework or repair of vendor supplied equipments, fill in information below:				<b>Distribution</b>			
#Hours		\$Est Labor		\$G&A		<b>Cog</b>	J. Chrzanowski
\$Material		\$Burden		\$Total		<b>Insp</b>	Phelps C
Disposition By				Chrzanowski J	Date	09/08/06	
Supervisor's Concur				Reiersen W	Date	09/08/06	
Eng. Dept. Head Concur				Williams M	Date	09/08/06	
WCO/Other				N/A	Date		
PQA/QC Mgr Dispos Concur				Boscoe J	Date	09/11/06	
QC Field Verification By					Date		
Proj. Doc Control (when closed)							
QC Files							
Malsbury J							
Boscoe J							
T. Meighan							
Reiersen W							
Williams M							
Dudek L							
Tyrrell M							
Malinowski F							