



One side of the $\frac{3}{4}$ " section of T accepted a .018" shim. The maximum allowable gap is .005". This area was repaired using fiberglass filler and now a .005" shim will not pass through this area.

