

Rev 0-c: RFD-12-024 removed requirement to trim 6 seal plates on the VVSAs. Analysis confirmed that there was sufficient clearance to rotate MC over the VVSA without trimming.

