everson tesla incorporated

COIL # 1

EVERSON TESLA INC.

NCR # SC07017

NON-CONFORMANCE REPORT

Part No: 53023-005 Description: PPPL Wedge 5+6 PO/WO No: 303621

Supplier: Tesla Engineering LTD Date Rec'd: 4/9/07 Date Insp: 4/17/07

Prepared By: R. Brown Qty Rec'd: 2 Qty NC: 2

No.	Requirement	AQL	SS	Qty	Describe Non-Conformance
	Dwg SE131-085			2	Parts conform To drawing but do not comply To Plastic model that was machined To the low side of Tolerance, which fit ETI mold. Ref E-mail attached
	Tesla 130-01001				

Supplier Responsible? ☑ Yes ☐ No

Corrective Action Req'd? ☑ Yes ☐ No

Disposition: *(indicate qty)*

UAI	RTV	Screen
Rework ✓	Scrap	Repair

Customer Approval Req'd? ☐ Yes ☑ No

Customer Signature: _____ Date: _____

Remarks: Wedges were sent to Atlas for remachining and now fit in mold. Future wedges should be To low side of spec.

Corrective Action attached RBB 5/7/07

Approval:

Department	Signature	Date
Engineering	[signature]	5/3/07
Manufacturing		
Quality Assurance	[signature]	5/3/07

Distribution:

Storerm	✓		
Purch			
Prod Cntrl			

Original to be filed in QA

Verification Signature: R. Brown Date: 5/7/07

ETF021 Rev. 0 09/15/04

NOT A NON-CONFORMANCE WITH RESPECT TO PPPL DRAWINGS OR REQUIREMENTS. PART MEETS PPPL DRAWINGS M. Kalish 8/9/07