EVERSON TESLA INCORPORATED

NCR # SC07053

NON CONFORMANCE REPORT

Part No: 53028 Description: PPPL Coil #3 PO/WO No: 932

Supplier: ETI Date Rec'd: Date Insp: 9/27/07

Prepared By: R. Brown Qty Rec'd: 1 Qty NC: 1

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	VPI Fill				Coil #3 Outer Area.
					dry glass/Air

Supplier Responsible? ☑ Yes ☐ No

Corrective Action Req'd? ☐ Yes ☐ No

Disposition: *indicate qty*

UAI	RTV	Screen
Rework	Scrap	Repair ✓

Customer Approval Req'd: ☑ Yes ☐ No

Customer Signature: M. [signature] 10/2/07 P. Hetzenwalder ~~Date~~ 10/3/07

Remarks: Coat coil areas between SS wedges and G-11 lead block with CTD 540 resin. After resin has cured, perform Cold Test per MPO "53028 Cold Test Rev 1".

Approval:

Department	Signature	Date
Engineering	[signature]	10/1/07
Quality Assurance	Roger Brown	10/1/07

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: Date:

ETF021 Rev. 0 09/15/04