EVERSON TESLA INCORPORATED

NCR # SC08007

NON CONFORMANCE REPORT

Part No: 53028 Description: PPL Coil #9 PO/WO No: 938

Supplier: ETI Date Rec'd: 2/18/08 Date Insp: 2/18/08

Prepared By: R. Brown Qty Rec'd: 1 Qty NC: 1

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	VPI Filler				Coil #9 - Area of dry glass See attached pictures

Supplier Responsible?
☑ Yes ☐ No

Corrective Action Req'd?
☐ Yes ☒ No

Disposition: *indicate qty*

UAI	RTV	Screen
✓		
Rework	**Scrap**	**Repair**
PER EVERSON PROCEDURE	DURE ATTACHED MK	

Customer Approval Req'd: ☑ Yes ☐ No

Customer Signature: Michael Ulm 2/26/08 P. Dalgaard Date: 2/26/08

Remarks: Coil passed 13.5 KV HIPOT Test.

Approval:

Department	Signature	Date
Engineering	John Stafford	2/18/08
Quality Assurance		

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: _____ Date: _____