TF COIL # 8 + # 10

EVERSON TESLA INCORPORATED

NCR # SC08010

NON CONFORMANCE REPORT

Part No: 53028-005 Description: PPPL Wedges W19 + W20 PO/WO No: 303621

Supplier: Tesla Date Rec'd: 2/26/08 Date Insp: 2/26/08

Prepared By: R. Brown Qty Rec'd: 2 Qty NC: 2

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	PPPL Dwg				Nickel content exceeds
	SE-131-085				specification - Spec 13.5/14.0 %
					Actual is 14.2 %
	Tesla 130-D1001				

Supplier Responsible?
☑ Yes ☐ No

Corrective Action Req'd?
☐ Yes ☐ No

Disposition: *indicate qty*

UAI ✓	RTV	Screen
Rework	Scrap	Repair

Customer Approval Req'd: ☒ Yes ☐ No

Customer Signature: Michel Lin 2/26/08 P. Dwiggins Date: 2/26/08

Remarks:

Approval:

Department	Signature	Date
Engineering	John Stafford	2/26/08
Quality Assurance		

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: Date:

ETF021 Rev. 0 09/15/04