EVERSON TESLA INCORPORATED

NCR # SC08043

NON CONFORMANCE REPORT

Part No: 53028-005 Description: SS WEDGE SET PO/WO No: 303621

Supplier: TESLA Date Rec'd: 7/24/08 Date Insp: 8/5/08

Prepared By: JOHN STAFINIAK Qty Rec'd: 1 SET Qty NC: 1 WEDGE #24

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
				1	.04" of extra material is missing from 10° surface. This extra material is needed to ensure complete cleanup at final machining after assembly.
					REF: COIL #17
					WEDGE #24

Supplier Responsible?

☑ Yes ☐ No

Corrective Action Req'd?

☐ Yes ☑ No

Disposition: *indicate qty*

UAI	RTV	Screen
Rework	Scrap	Repair ✓

Customer Approval Req'd: ☑ Yes ☐ No

Customer Signature: _____ Date: _____

Remarks: Place .020" shim (glass tape) between coil and wedge and to G-11 blocks between wedges. Also, place .020" shim between wedge and mold.

Approval:

Department	Signature	Date
Engineering	John Stafiniak	8/7/08
Quality Assurance		

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: _____ Date: _____

ETF021 Rev. 0 09/15/04