**MUST USE v5.0 HaspX.exe 2009**

TO UPDATE USB SIM when using Verisurf CD or email attachment:
To update your SIM/HASP you will need to run the HASPX.exe program (v5.0) which can be
found on the Verisurf X CD or has been emailed as a file named Haspx.piz. Most email filters will
not accept an executable file so it has been named HASPX.piz. You will need to rename .zip,
then extract the haspx.exe file.   http://updates.mastercam.com/x4/release/haspx.exe

Troubleshooting:

If you receive a message upon starting Verisurf: **HASP not found**

Use the Windows Start/Run, browse and locate the Verisurf or MCAM9 folder/Common/hinstall.
Once you have selected the hinstall you will need to type (space) -i