Customer: PRINCETON PLASMA PHYSICS LAB

Contact: LARRY SUTTON E-Mail: S-04286-F

Reported By: DOUG MCCORKLE

Part: / SE122-104-1 PORT 12 COVER Drawing ID: SE122-072 Revision: 1 Telephone: 609-243-2441 Fax: 609-243-2021

Customer P.O.: S005243-F/Ln:9 Serial No:9/294

m

Telephone: 317-636-6433 Fax: 317-634-9420

E-Mail: dMcCorkle@MajorTool.com

Problem: PER B.P. MAGNETIC PERMEABILITY TO BE LESS THAN 1.02

PERMEABILITY ON PART CHECKS GREATER THAN 1.2 BUT LESS THAN 1.4

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of additional	pages:
----------------------	--------

Customer Disposition:	[] Use As Is	[] Rework	[] Repair	[] Scrap	[] Replace		
Tashnisal Contast	Annuovali		,	Titlet		Doto	
Technical Contact				Title <u>:</u>		Date:	-
Buyer	Approval:			Title <u>:</u>		Date:	-
Major Tool Implen	nented By:		,	Title <u>:</u>		Date:	

Nonconformance Report: Major Tool NC19149

This is for / SE122-104-1 PORT 12 COVER

Problem:

PER B.P. MAGNETIC PERMEABILITY TO BE LESS THAN 1.02

PERMEABILITY ON PART CHECKS GREATER THAN 1.2 BUT LESS THAN 1.4

Doug McCorkle

Project Disposition:

Accept as is.

Approvals:

Procurement Technical Representative

Art Brooks, Technical Assurance

Responsible Line Manager:

Project Quality Assurance: