

Everson
Tesla
Incorporated

NCR # SC07034

EVERSON TESLA INC.

NON-CONFORMANCE REPORT

Part No: 53028 Description: PPPL COIL # 2 PO/WO No: 931
Supplier: ETI Date Rec'd: _____ Date Insp: 7/17/07
Prepared By: R. Brown Qty Rec'd: 1 Qty NC: 1

No.	Requirement	AQL	SS	Q5	Describe Non-Conformance
	PPPL # SE131-003				① O-Ring Material
	ET # 53028				
	Coil # 2				② Separation of wedge from coil # 2 at the conclusion of the one step VPI

Supplier Responsible?
 Yes No
 Corrective Action Req'd?
 Yes No

Dispositions (Indicate qty)

UAI	RTV	Scrap
Rework	Scrap	Repair

Customer Approval Req'd? Yes No Date: 8/28/07

Customer Signature: Martin Lewis
Remarks:
- WEDGES REMOVED BY PRESSING BACK INTO SHAPE AND W/FT WRAPPING COIL
- O RING MATERIAL USED IN MOLD NOT CHANGED AS REQUESTED. MATERIAL CORRECTED FOR COIL # 3

Approval

Department	Signature	Date
Engineering		
Manufacturing		
Quality Assurance		

Distribution

Storem		
Purch		
Prod Cntrl		

Original to be filed in QA

Verification Signature: _____ Date: _____