

Everson
 3110
 Incorporated

EVERSON TESLA INC.

NCR # 5C0704-3

NON-CONFORMANCE REPORT

Part No: 53028 Description: PPFL Coil #2 PO/WO No: 931
 Supplier: ETT Date Rec'd: _____ Date Insp: 8/17/07
 Prepared By: R. Brown Qty Rec'd: 1 Qty NC: 1

No.	Requirement	AQL	SS	Qty	Describe Non-Conformance
	PPFL # SE131-003				ET 53028 MRO Rev. 0 3/5/07
	ET # 53028				Page 12 of 44
	Coil #2				Operation - 029
					Location 3.602" +/- .030"
					1 +28" 3.570"
					2 +14" 3.570"
					3 +5" 3.568"
					4 -5" 3.570"
					5 -14" 3.570"

Supplier Responsible?

Yes No

Corrective Action Req'd?

Yes No

Disposition: (Indicate qty)

UAI <input checked="" type="checkbox"/>	RTV	Screen
Rework	Scrap	Repair

Customer Approval Req'd?

Yes No

Customer Signature: M. W. ... / RLM MR Date: 8/30/07

Remarks: ACCEPTING PART WITH OUT OF TOLERANCE
OF .002" TO .004" CAREFULLY EVALUATING PROCS
TO DETERMINE IF THIS IS A PROCESS ERROR
AND CORRECTING AS NECESSARY.

Approval:

Department	Signature	Date
Engineering	<u>[Signature]</u>	<u>8/27/07</u>
Manufacturing		
Quality Assurance		

Distribution:

Storem		
Purch		
Prod Cntrl		

Original to be filed in QA

Verification Signatures: _____

Date: _____