

EVERSON TESLA INCORPORATED

NCR # 508032

NON CONFORMANCE REPORT

Part No: 53028 Description: PPPL COIL #13 PO/WO No: 303621
 Supplier: TESLA Date Rec'd: 5/21/08 Date Insp: 5/21/08
 Prepared By: [Signature] Qty Rec'd: 1 Qty NC: 1

No	Requirement	AQL	SS	Qty	Describe Non-Conformance
	DWG. NO.				
	53028-COIL				
	LOCATION #19				
	51.88 ± .030				15: 51.907 (OK) - INFO ONLY
	LOCATION #20				
	51.88 ± .030				15: 51.766 - 15 .084 U.L.L.
					NOTE 2x 51.88 ± .030
					103.76 ± .060
					15: 103.67, 103 U.L.L.

Supplier Responsible?

Yes No

Corrective Action Req'd?

Yes No

Disposition: indicate qty

UAI	RTV	Screen
Rework	Scrap	Repair

Customer Approval Req'd: Yes No

Customer Signature: [Signature] 5/21/08

Date: [Signature] 5/22/08

Remarks:

Approval:

Department	Signature	Date
Engineering	<u>[Signature]</u>	5/21/08
Quality Assurance		

Storeroom			
Purchasing			
Prod Cntrl			

Original to be filed in QA

Verification Signature: _____

Date: _____