
Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-116 / MODULAR COIL WINDING FORM TYPE

Drawing ID: SE141-116

Revision: 7

Customer P.O.: S005242-F/Ln:2
Serial No./Qty: C2

Reported By: MIKE GRIFFITH

E-Mail: mGriffith@MajorTool.com

Telephone: 317-636-6433

Fax: 317-634-9420

Problem: THERE ARE NOT ENOUGH DATA POINTS IN THE POINT CLOUD SURFACES TO MATCH THE REQUIREMENT OF 4" X 4" ON AS-CAST SURFACES.

Proposed Disposition:

CUSTOMER TO ADVISE THE ACCEPTABILITY OF NOT HAVING ENOUGH DATA POINTS.

Number of additional pages: _____

Customer Disposition: Use As Is Rework Repair Scrap Replace

This data will be accepted for C2. PPPL will take additional measurements upon receipt to fill in the gaps in the data provided. However, EIO is requested to take corrective actions to assure that the metrology data on all future winding forms comply with the specified requirements.

Tech. Rep. Approval:

RLM Approval:

Major Tool Implemented By: _____ **Title:** _____ **Date:** _____