PPPL NONCON	FORMANCE R	EPORT NO:	3681	Open D	ate	11/10/06		
-	9 - Closed NCR			Trend	01-De	viation Fron	n Doc/Proc	
-	NCSX			Division	WBS 1	141		
-	/ENDOR							
Item Dwg/Part#	SE141-115 R9	Procu	rement #	S00524	2-F		<b>Cost Cente</b>	9450 1*** 1404
RAP# 3209	Job Doc # <u>SC</u>	05242-F	Vendor	Energy Inc	dustries	of Ohio		
RAP Title NCSX -	Modular Coil Windin	g Forms						
☐ HoldTag Appl	ied							
Nonconforming C	ondition (includ	e requirement(s)	violated)	<u>:</u>				
MCWF-B1-Drawing SE following areas were Datum D side Clamps 73 to 74 Larg Clamps 21 to 33 Larg Datum E side Polodial break to Clamps 73 to 84 Larg Clamps 73 to 84 Larg Clamps 59 to 64 Larg Clamps 18 to 24 Step Clamps 7 to Pol. Bk.  Lot Size Recd  Reported By Ph	found to either have ger than 1/8" radius ger than 1/8" radius np 95 Step/slope co ger than 1/8" radius ger than 1/8" radius ger than 1/8" radius b/slope condition Larger than 1/8" rad	gauge gauge gauge ndition gauge gauge gauge	n 0.125" or		ence (st	ep or slope		dius.
Disposition: Rework			<u> </u>			Valle		Rework
inspected by QC prior	to completion.							
For rework or repair	of vendor supplied	l equipments, fill i	n informati	on below:			<u>Distri</u>	bution
#Hours	\$E	st Labor	\$	G&A			Cog	Heitzenroeder P
\$Material		urden	\$ <sup>.</sup>	Total	\$320	<del>_</del>	1 -	Doc Control (when
Disposition By	Chr	zanowski J			Date	11/15/06	closed	
Supervisor's Cond	cur Nels	on B			Date	12/08/06	Malsb	•
Eng. Dept. Head C		ams M		г	Date	12/09/06	Bosco Chrza	e J nowski J
WCO/Other					Date		Nelso	n B
	<u>N/A</u>						Reiers Willian	
POA/OC Mar Diag	os Consur				Dete		Sutto Lumb	n L erger J
PQA/QC Mgr Disp	<u>-</u>	Malinowski F			Date	12/11/06		
QC Field Verificati	ion By	Phelps C			Date	01/05/07		owski F