
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Mike Viola
E-Mail: mviola@pppl.gov

Telephone: 609-243-3655
Fax: 609-243-3248

Part: 130093 / CONFLAT FLANGE, 12.0 OD TAPPED

Drawing ID: SE120-004

Revision: 1

Customer P.O.: S005243-F
Serial No./Qty: 1 Piece

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: 1.02 MAX MAGNETIC PERMEABILITY: PART CHECKS 1.02 ON THE O.D.
PART CHECKS GREATER THAN 1.4, BUT LESS THAN 1.6 ON THE I.D.

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of additional pages: _____

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____