
Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Mike Viola
E-Mail: S-04286-F

Telephone: 609-243-2441
Fax: 609-243-2021

Part: SE122-149 / PORT 4 COVER PLATE

Drawing ID: SE122-149 Revision: 2

Customer P.O.: S005243-F/Ln:9
Serial No.: 9/2

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: 1.25 +/-0.01 THICKNESS MEASURES 1.232-1.247

Proposed Disposition:

CUSTOMER DISPOSITION REQUIRED

Number of additional pages: 0

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____

Nonconformance Report: Major Tool NC18787

This is for SE122-149 / PORT 4 COVER PLATE

Problem:

1.25 +/- .01 THICKNESS MEASURES 1.232-1.247

Best Regards,
Doug McCorkle

Project Disposition:

May be used as is.

Approvals:

Procurement Technical Representative

Responsible Line Manager: