

Nonconformance Reports:

Major Tool NCs:

17157, 17288, 17287, 17286, 17240, 17237, 17233, 17167, 17314, 17342

Project Disposition:

Substitute Trinos flanges per Contract change order #1 S5243 c-o 1 dated 6/22/2005.

Approvals:

Mike Viola

Digitally signed by Mike Viola
DN: CN = Mike Viola, C = US
Reason: I have reviewed this document
Date: 2005.08.22 13:41:12 -0400

Procurement Technical Representative

Brad Nelson

Digitally signed by Brad Nelson
DN: cn=Brad Nelson, c=US, o=CRRL, ou=FED,
email=bradn@crri.gov
Date: 2005.08.22 13:59:29 -0400

Responsible Line Manager:

Customer: PRINCETON PLASMA PHYSICS LAB

Contact: Mike Viola
E-Mail: mviola@pppl.gov

Telephone: 609-243-3655
Fax: 609-243-3248

Part: 110058 / CONFLAT BLANK FLANGE, 12.0 DIA

Drawing ID: SE120-004 Revision: 1

Customer P.O.: S005243-F
Serial No./Qty: 9 Pieces

Reported By: DOUG MCCORKLE
E-Mail: dMcCorkle@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: 1.02 MAX MAGNETIC PERMEABILITY
PARTS CHECK GREATER THAN 1.05 AND LESS THAN 1.1

Proposed Disposition:
CUSTOMER DISPOSITION REQUIRED

Number of additional pages: _____

Customer Disposition: Use As Is Rework Repair Scrap Replace

Technical Contact Approval: _____

Title: _____ **Date:** _____

Buyer Approval: _____

Title: _____ **Date:** _____

Major Tool Implemented By: _____

Title: _____ **Date:** _____