

Customer: ENERGY INDUSTRIES OF OHIO

Contact: NANCY HORTON
E-Mail: NKHFlowen@aol.com

Telephone: 216-496-2314
Fax: 216-328-2001

Part: SE141-115 / MODULAR COIL, TYPE B

Drawing ID: SE141-115 Revision: 8

Customer P.O.: S005242-F/Ln:2
Serial No./Qty: B2

Reported By: MIKE GRIFFITH
E-Mail: mGriffith@MajorTool.com

Telephone: 317-636-6433
Fax: 317-634-9420

Problem: Sheet 7, zone B3; three of the 3/8-16 UNC-2B holes cannot be machined into the casting pad. The machining qualification relative to the cast stock resulted in a shift of approximately .350" from the ideal location for this feature.

Attatch is the MTM proposal for the rework of this area.

Proposed Disposition:

PROPOSE TO REPAIR PER ATTACHMENT.

Number of additional pages: 1 page rework proposal

Customer Disposition: ☐ Use As Is ☒ Rework ☐ Repair ☐ Scrap ☐ Replace

[illegible]

Approved by:

Tech. Rep.

RLM

Major Tool Implemented By: _____ **Title:** _____ **Date:** _____