| PPPL NONCONF | FORMANC | E REPORT | NO: 36 | 685 | Open D | ate | 11/30/06 | | | |
|---|------------------------------|----------------|-------------------|---------|---------------|----------------------------|------------|---------------|---|----------|
| _ | 5 - Corrective Action Needed | | | | Trend | 01-Deviation From Doc/Proc | | | | |
| _ | ICSX | | | | Division | WBS 1 | 141 | | | |
| _ | /ENDOR | | | | | | | | | |
| _ | D-NCSX-MCF-00 | 1 Rev. 03 | Procureme | ent # | S00524 | 2-F | | Cost Cen | 9450 1*** 140 | 4 |
| RAP# 3209 | Job Doc # | S005242-F | Ve | ndor | Energy Inc | dustries | of Ohio | | | |
| RAP Title NCSX - N | Modular Coil Wi | nding Forms | | | | | | | | |
| ☐ HoldTag Appli | ied | | | | | | | | | |
| Nonconforming Co | ondition (inc | lude require | ment(s) viol | ated): | <u> </u> | | | | | |
| the inside of one of th Representative picture | | | | o O | as were rou | | ejected | | ejected 0 | |
| | elps C | - | | Malino | . L | Lot K | | dated Date | | _ |
| Disposition: Rework | | | | | | * | van | uatou But | Chrzanowski J | <u> </u> |
| The lip found on the in | nside of one of | the lead block | siots was remo | ovea (: | see attached | a emaii | from J. Cr | irzanowski). | y | |
| For rework or repair o | of vendor sup | olied equipme | nts, fill in info | ormatio | on below: | | | Dis | <u>stribution</u> | |
| #Hours | | \$Est Labor | | \$0 | G&A | | | Co | | |
| \$Material | | \$Burden | | \$7 | Γotal | | · | | sp <u>Chrzanowski J</u> oj. Doc Control (when | |
| | | | | | - | | | clo | osed) | |
| Disposition By | | Chrzanowski J | | | | Date | 01/19/07 | "" | C Files | |
| Supervisor's Conc | | |) | | - | | 01/19/07 | , Ma | alsbury J | |
| Cupo. Moo. C Como | ur | Nelson B (RLM) | | | | Date | 01/17/07 | _{Bo} | • | |
| Eng. Dept. Head C | | Williams M | , | | | Date Date | 01/29/07 | Bo: | elson B | |
| - | oncur | | | | | | | Me Rei | scoe J | |

A4 High Magnetic Permeability Areas and Lead Block Slot Lip NCR 11/30/06








Page 1 of 4



Page 2 of 4







Lead Block Slot Lip



Page 4 of 4